

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: claims@carsmith.biz

VEHICLE NO: SLC9786Z

MAKE & MODEL: KIA FORTE

DOA: 20.12.2024

CLAIM TYPE: TP CLAIM

Not Authorized
den
merang
24/12/24
1/5 \$3800
H days

ESTIMATION QUOTE

nett

PARTS	QTY	PRICE (\$)	REMARKS
REAR BOOTLID	1	\$ 1,245.00	Bent/wiped
REAR BOOTLID HINGE LH	1	\$ 125.00	11 X
REAR BOOTLID HINGE RH	1	\$ 125.00	11 X
REAR BOOTLID INSULATOR	1	\$ 213.00	11 X
REAR BOOTLID LOCK	1	\$ 390.00	11 X
REAR BOOTLID INNER LAMP LH	1	\$ 409.00	11 X
REAR BOOTLID INNER LAMP RH	1	\$ 409.00	11 X
REAR BOOTLID WEATHERSTRIP	1	\$ 219.00	11 X
REAR BOOTLID NUMBER PLATE LAMP LH	1	\$ 54.00	11 X
REAR BOOTLID NUMBER PLATE LAMP RH	1	\$ 54.00	11 X
REAR BOOTLID STOPPER	2	\$ 48.00	11 X
REAR BOOTLID LAMP LH	1	\$ 389.00	Repetit X
REAR BOOTLID LAMP RH	1	\$ 389.00	Repetit X
REAR BUMPER	1	\$ 795.00	Dis
REAR BUMPER RETAINER RH	1	\$ 65.00	11 X
REAR BUMPER SPONGE reinforcement bracket RH	1	\$ 155.00	Bent/wiped
REAR BUMPER REINFORCEMENT	1	\$ 384.00	CNO
REAR BUMPER LOWER GARNISH	1	\$ 508.00	Dis
REAR BUMPER REFLECTOR RH	1	\$ 256.00	CNO
REAR BUMPER REFLECTOR COVER RH	1	\$ 193.00	11 X
REAR FENDER RH	1	\$ 1,828.00	R X
REAR FENDER INNER SHIELD RH	1	\$ 278.00	11 X
REAR TAILLAMP LH	1	\$ 498.00	11 X
REAR TAILLAMP RH	1	\$ 498.00	11 X
REAR TAILLAMP PANEL LH	1	\$ 299.00	11 X
REAR TAILLAMP PANEL RH	1	\$ 299.00	11 X
END PANEL	1	\$ 694.00	Dis/Bent
END PANEL TOP GARNISH	1	\$ 219.00	11 X
REAR EXHAUST MOUNTING	1	\$ 108.00	11 X
REAR EXHAUST MUFFLER	1	\$ 2,250.00	11 X

\$ 13,397.00

LESS 10% \$ 1,339.70

SUB TOTAL \$ 12,057.30

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR NUMBER PLATE	1	\$ 100.00	11 X
REAR BUMPER CLIP	1 SET	\$ 40.00	Re 30 S/N
REAR FENDER INNER TRIM CLIP	1 SET	\$ 40.00	11 X
BOOTLID INSULATOR CLIP	1	\$ 30.00	11
REAR REVERSE SENSOR	1 SET	\$ 400.00	Mol/factor 200 S/N
SUB TOTAL		\$ 610.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ALL WIRING AND LIGHTING SYSTEM	1	\$ 150.00	20
REMOVE, RENEW CONDENSER AND TOP UP GAS	1	\$ 150.00	11 X
REMOVE, REFIT REAR LINING, TRIM AND GARNISH	1	\$ 200.00	60
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 150.00	30
REMOVE AND STRAIGHTEN REAR EXHAUST	1	\$ 150.00	11 X
REMOVE AND RENEW FLOOR INSULATOR	1	\$ 150.00	11 X
TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	1	\$ 250.00	50
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,500.00	600
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,500.00	850
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 150.00	X

SUB TOTAL \$ 4,350.00

GRAND TOTAL \$ 17,017.30

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts, before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 3240
102
2925
230
1610
4765
282
3812