

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email:

sngahtee@singnet.com.sg; darren@sngahtee.com; admin@sngahtee.com; admin2@sngahtee.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF24B00000200	Date of Loss:	13/12/2024
Vehicle Reg. No.:	GBE3030T	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NEO GLOBAL PTE. LTD.		
Driver:	SAW HENARY HTOO		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	26/10/2015
Vehicle Colour:	SILVER	Chassis No:	JTFAT35Y20K205228
Engine No:	1KD2561802		
Odometer:	2982 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Remarks:	VEHICLE AT WORKSHOP		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	4,973.80
Miscellaneous Items	0.00
Labour	3,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,383.80
+ GST 9.00% (S\$)	754.54
Nett Amount (S\$)	9,138.34

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tanfik 97495745 24/12/24 3pm
Not approve Ex \$600
L/S Repair after repair 7 days
tanfik e/khauto.m

Tanjah LKR

OD ECLCS

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Dec 2024)
 Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3030T/18/12/2024 17:57
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt - *25.00 FS
2	1		*FRT BUMPER	0.00	0.00	de - *220.00 F
3	1		*FRT BUMPER BRACKET	0.00	0.00	bt - *100.00 F
4	1		*FRT GRILLE	0.00	0.00	cur - *180.00 F
5	1		*FRT GRILLE EMBLEM	0.00	0.00	ner - *45.00 F
6	1		*FRT GRILLE TOP SEAL	0.00	0.00	ner - *48.00 F
7	10		*FRT GRILLE CLIPS (+)	0.00	0.00	ner - *80.00 F
8	10		*FRT GRILLE CLIPS (-)	0.00	0.00	nn - *80.00 F
9	2		*FRT HEADLAMP	0.00	0.00	cray LH - RH Cur X *680.00 F pro
10	2		*FRT HEADLAMP LOWER SEAL	0.00	0.00	out - *50.00 F
11	1		*FRT PANEL CPL	0.00	0.00	bt - *1,200.00 F
12	1		*FRT CORNER PANEL LH	0.00	0.00	bt - *75.00 F
13	1		*FRT PANEL CENTER GARNISH	0.00	0.00	out - *120.00 F
14	2		*FRT PANEL SIDE GARNISH	0.00	0.00	LH Xnn RH de - *90.00 F \$45
15	1		*FRT WIPER GARNISH	0.00	0.00	bt - *150.00 F
16	2		*FRT WIPER GARNISH SIDE COVER	0.00	0.00	LH Xnn RH Cur X *100.00 F \$50
17	2		*FRT WIPER ARM	0.00	0.00	nn X *140.00 F
18	2		*FRT WIPER ARM BLADE	0.00	0.00	nn X *50.00 F
19	2		*FRT WIPER NOZZLE	0.00	0.00	nn X *40.00 F
20	2		*FRT WIPER NOZZLE NUT	0.00	0.00	nn X *20.00 F
21	1		*FRT WIPER LINKAGE	0.00	0.00	Xnn ? *160.00 F
22	1		*FRT SIDE MIRROR ARM LH	0.00	0.00	bt - *200.00 F
23	2		*FRT DOOR ROC STICKER	0	0.00	out - *100.00 FS
24	1		*FRT AIRCON BLOWER ASSY	0.00	0.00	Xnn ? *580.00 F

F=Franchise part, S=SpcNett.

Sub Total (S\$) \$3243.00 4,533.00
 + Margin on L,N Items 10.00% (S\$) add 10% = \$3567.30 440.80

Total Parts (S\$) \$4612.51 4,973.80

Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3030T/18/12/2024 17:57. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK FRT DOOR X 2 , FRT FLOOR PANEL,WELD,REMOVE & REPLACE ABOVE PARTS	New 1000	1,400.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New 1000	1,400.00
3	TO CHECK WIRING	New 30	50.00
4	TO DIAGNOSE AND RESET FAULT CODE	New 150	180.00
5	TO REMOVE & REFIX FRT DASHBOARD	NewXnn 200?	280.00X
6	TOP UP AIRCON GAS	New Xnn ?	100.00X
Gross Labour Cost (S\$)			12,410.00 3,410.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3030T/18/12/2024 17:57. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$4872.30
14% 20% = \$4697.84
A \$4697.84
before tax \$600
or? the amount.
Shann
14/3/25.