

LEANG AUTOMOTIVE  
 BLK 1 KAKI BIKIT AVE 6 #01-68  
 AUTOBAY S'PORE 417883 HP 90286516

not Authorized  
 all  
 mercury  
 24/11/24  
 5-days d/s \$3900 /  
 telephone advisory

VEHICLE No: SMA 5606K

PLEASE CHECK PARTS PRICE

1PC	REAR WINDSCREEN MOULDING	new body	\$80.60	✓
1PC	TAILGATE		\$903.20	✓
1PC	TAILGATE 'JAZZ' EMBLEM	new	\$56.80	✓
1PC	TAILGATE 'H' LOGO	new	\$45.00	X
1PC	TAILGATE OUTER HANDLE GARNISH	new	\$280.00	X
1PC	TAILGATE INNER LOCK	Daye	\$109.80	✓
1PC	TAILGATE LOCK STRIKER	new	\$66.00	X
1PC	TAILGATE INNER TRIM BOARD	before	\$291.80	✓
1SET	TAILGATE INNER TRIM BOARD CLIPS	new	<del>\$20.00</del>	✓
1PC	TAILGATE WEATHERSTRIP	new	\$148.50	✓
1PC	REAR BUMPER	before	\$540.50	✓
1PC	REAR BUMPER LOWER	new	\$302.00	✓
2PCS	REAR BUMPER SIDE RETAINERS @ \$25.00	new	\$50.00	X
1SET	REAR BUMPER CLIPS	new	<del>\$50.00</del>	✓
1PC	REAR END PANEL	new	\$386.80	✓
1PC	REAR END PANEL TOP GARNISH	new	\$169.80	✓
2PCS	TAILLAMPS @ \$366.20	new	<del>\$732.40</del>	✓ \$366.20
1PC	REAR BUZZLE SENSOR	new	\$98.00	X
2PCS	REAR FENDER INNER TRIM BOARDS @ \$395.00	new	\$790.00	X
1PC	REAR FLOOR PANEL	new	\$1,280.00	X
1PC	REAR FLOOR PANEL TOP BOARD	new	\$382.00	X
1PC	REAR FLOOR PANEL TOOLS SPONGE	new	\$485.00	X
			\$7,278.20	
	LESS 20%		\$5,822.56	

S.NETT

1PC	REAR WINDSCREEN SEALANT	new	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	new	\$50.00	20
1PC	REAR END PANEL SEALANT	new	\$50.00	40
1SET	REAR BUMPER REVERSE SENSOR	new	\$280.00	X

	TO CEHCK WIRING		\$50.00	20
	TO DISMANTLE & REPLACED REVERSE SENSOR		\$80.00	30
	TO DISMANTLE & REFX REAR WINDSCREEN		\$150.00	120
	TO TRANSFER TAILGATE MECHANISM		\$100.00	60
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	60
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	new	\$180.00	X
	TO DISMANTLE & REFIX REAR EXHAUST	new	\$100.00	X
	TO SPRAY RUST PROOFING		\$100.00	50
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$1,000.00	600

TO PUTTY & SPRAY PAINTING

TOTAL

\$1,500.00 ~~800~~ \$600  
\$9,632.56

LKK Auto Consultants hence notify  
the Repairer of the following:

- To recurvey before/after spray painting
- To display damaged parts, with warranty
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be restorated and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-3802-2  
20%  
3041-76  
100  
1740