

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

not Authorized
in
merch
26/12/24
1/5 @ 2300/
2 days
24/12/24

VEHICLE NUMBER: YN2770C

MAKE & MODEL: MITSUBISHI FE85DJZRDEA

FRONT CORNER PANEL TOP COVER RH	DO		\$434.30	
FRONT SIGNAL LAMP RH	BW	366.01	\$581.60	
FRONT SIDE LAMP RH	BW	282.40	\$311.20	
FRONT HEADLAMP RH	11		\$1,138.90	X
FRONT BUMPER	BW	1233.10	\$1,431.40	
FRONT BUMPER BRACKET RH	11		\$280.70	X
FRONT FOG LAMP RH	11		\$296.40	X
FRONT DOOR RH	R		\$2,314.50	X
FRONT DOOR WINDOW RUBBER MOULDING RH	11		\$285.60	X
STEP PANEL GARNISH RH	11		\$356.70	
			\$7,431.30	
		Less 25%	\$1,857.83	
			\$5,573.48	

FRONT CORNER PANEL TOP COVER CLIPS RH	11		\$50.00	X
FRONT DOOR TRIMBOARD CLIPS RH	11		\$80.00	X
FRONT DOOR OUTER PROTECTOR CLIPS RH	11		\$50.00	X
FRONT DOOR COMPANY LOGO STICKER RH	11		\$600.00	X
STEP PANEL GARNISH RH CLIPS	11		\$50.00	X
			\$830.00	

TO PROVIDE LABOUR, WORKMANSHIP		\$800.00	300	
TO SPRAY PAINT ON AFFECTED PANELS		\$800.00	500	
RUST PROOFING		\$60.00	X	
TO CHECK FRONT WIRING AND HEADLAMP LEVELING		\$50.00	20	
TO REMOVE, REFIT & TRANSFER FRONT RH DOOR FITTINGS TO NEW		\$100.00	X	
		\$1,810.00		

Total

\$8,213.48

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) after resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2672-57
252
2004-39
880
2884-39
202
2307