

(08/14/13) ref

ASS. REC. BY: Marcus

REF:

CS/FC124120368/Unp3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBT 10515

at Workshop m/s

Er201/12

of

Insured:

SHA 9091C

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$11k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

0021

Date:

Person Contacted:

LYA 6215

Vehicle: IN / OUT

Veh No:

FBT 10515

Yr Regn:

08/11/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha YZF 155

c.c

155

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

57122

T/Radio:

Insured / Std / NI / NA

Eng/No:

N/A

C/No:

MH3RG721000001049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110-70-17

R:

140-70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/12/24

D.O.I.

26/12/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 Body / N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/8/2020

20/1/25 4/5 @ 2800 incident repair and agree
(Red. \$2717.90, 497)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS. SL

Photos

Others

TOTAL

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	002I
Vehicle Details	
Vehicle No.:	FBT1051S
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Dec 2024
Vehicle Make:	YAMAHA
Vehicle Model:	YZF155
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	G3R2E0001054
Chassis No.:	MH3RG721000001049
Maximum Power Output:	-
Open Market Value:	\$2,924.00
Original Registration Date:	08 Nov 2021
First Registration Date:	08 Nov 2021
Transfer Count:	1
Actual ARF Paid:	\$439.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Nov 2031
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$9,052.00
COE Rebate Amount:	\$6,215.00
Total Rebate Amount:	\$6,215.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 26 Dec 2024

OK

Advertisement

1 Click on "START"

Motorcycles

10 search results for 'YAMAHA YZF155' in Singapore

Save this search ☐ 



YAMAHA YZF155

Motorcycles ▾

Sort: Best Match ▾

Body ▾

Make ▾

Condition ▾

Price ▾

Deal Option ▾

More filters 



Almost New Yamaha
YZF155 (May 2021)
S\$10,000 ~~S\$13,888~~

♡ 17



R15 V3 Yamaha YZF-R15
YZF155 VVA
S\$9,000 ~~S\$9,500~~

♡ 55



2023 Yamaha YZ125
S\$7,888

♡ 48



2019 Yamaha R15 YZF15
27k km
S\$8,000 ~~S\$8,500~~

♡ 20

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-36/37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

ESTIMATE COST OF REPAIR

Date: 23-Dec-24

Estimate no. 1568

Plate No. FBJ1051S

Model. R15V

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	Exhaust CAP	\$ 45.00	✓	
2	PROTECTOR	\$ 85.00	✓	
3	SHIFT PEDAL	\$ 125.00	✓	
4	STEERING CONE	\$ 180.00	✓	
5	FRONT FORK (L, H)	\$ 850.00	✓	
6	FRONT FORK (R, H)	\$ 850.00	✓	
7	UNDER BRACKET COMPS	\$ 280.00	✓	
8	HANDLE BAR (L, H)	\$ 85.00	✓	
9	HANDLE BAR (R, H)	\$ 85.00	✓	
10	LEVER CLUTCH	\$ 28.00	✓	
11	LEVER BRAKE	\$ 28.00	✓	
12	FRONT FOOTREST R	\$ 45.00	✓	
13	FRONT FOOTREST L	\$ 45.00	✓	
14	PEDAL BRAKE	\$ 85.00	✓	
15	BRACKET 2	\$ 125.00	✓	
16	BRACKET 1	\$ 125.00	✓	
17	BODY FRONT UPPER	\$ 185.00	✓	
18	REAR FLASHER LIGHT	\$ 45.00	✓	
19	FRONT FLASHER LIGHT R	\$ 45.00	✓	
20	FRONT FLASHER L	\$ 45.00	✓	
21	FRONT ACE	\$ 45.00	✓	
22	COVERSET	\$ 2,000.00	✓	
23	LABOUR	\$ 700.00	✓	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Less 10% \$ 613.10
 Sub Total : \$ 5,517.90
 GST 9% \$ 496.61
 Total: \$ 6,014.51

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

not Authorised
 nra
 90096608
 1/5 #2800
 4 hrs.

2-3576
 10%
 3218.40
 320
 3538.4
 202
 2800