

ASS. REC. BY:

REF:

SMO/

CS/SMO24120381/Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

12/30

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKA 35112

Yr Regn:

02 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Per Seha Carrens 716.c 3614

Colour

M.O. Blue

AC:

Insured / Std / NI / NA

Sp. Reading

69826

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WPO888998AS700139

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

235/35 ZRA

R:

295/30 ZRA

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / (P/R) SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

9

mm

L/Bal.

8

mm

L/Bal.

9

mm

D.O.A.

28/12/24

D.O.I.

26/12/2024

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S 141

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

13/1 L/Rp @ 14,200 Calm (Red, @ 21443.20, 60%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech Invs

(\$

☐

: Weekend

(\$

Report Format:

Lump Sum / I.B.I. (\$

KBS Motorsports Pte Ltd



YOUR REF.: SGH6194L

OUR REF.: SKA3511L

TO: SOMPO INSURANCE

CC: Claims Services Department

FAX:

*Not withheld
L1 Smg & 14,200k
Paying After Pairs
5 days*

DATE: 26/12/2024
FROM: Lee Shirley
FAX: 6452 5333
CONTACT: 8686 5188
MAKE & MODEL: PORSCHE 911 CARRERA 3.6 A
CHASSIS NO.: WP0ZZZ99ZAS700139
ENGINE NO.: MA102A01008
YEAR MADE: 2011
ACCIDENT DATE: 24 December 2024

ESTIMATE FOR VEHICLE NO.: SKA3511L

NO.	DESCRIPTION	QTY.	LIST PRICE
1	FRONT BUMPER <i>3550</i>	1	\$ <i>Bucl Del</i> 7,040.00 ✓
2	FRONT BUMPER TRIM LH	1	\$ <i>Del</i> 66.00 ✓
3	FRONT BUMPER RETAINING FRAME	1	\$ <i>Ln</i> 770.00 ✓
4	FRONT BUMPER RETAINING FRAME LH	1	\$ <i>Dis</i> 290.00 ✓
5	FRONT BUMPER CARRIER	1	\$ <i>Ln</i> 3,630.00 ✓
6	FRONT BUMPER SHOCK ABSORBER	1	\$ <i>Ln</i> 400.00 ✓
7	FRONT BUMPER RETAINING STRIP CENTER	1	\$ <i>Ln</i> 400.00 ✓
8	FRONT BUMPER RETAINING STRIP LH	1	\$ <i>Dis</i> 100.00 ✓
9	FRONT BUMPER RETAINING PLATE LH	1	\$ <i>Ln</i> 125.00 ✓
10	FRONT BUMPER RETAINING TRIM LH	1	\$ <i>Ln</i> 25.00 ✓
11	FRONT BUMPER SIDE MARKER LIGHT LH	1	\$ <i>CM</i> 95.00 ✓
12	FRONT FOG LAMP LH <i>1280</i>	1	\$ <i>CM</i> 2,288.00 ✓
13	FRONT HEADLAMP LH <i>3310</i>	1	\$ <i>Ln</i> 7,260.00 ✓
14	FRONT FENDER LH <i>2100</i>	1	\$ <i>B1/Bucl</i> 3,410.00 ✓
<i>3650</i> 15	FRONT SPORT RIMS LH	1	\$ <i>Del</i> 5,400.00 ✓
TOTAL:			\$ 31,299.00
LESS 10%:			\$ (3,129.90)
PARTS TOTAL:			\$ 28,169.10
			\$ <i>nn</i> 80.00 X
TOTAL:			\$ 1,400.00 <i>500k</i>
			\$ 150.00 <i>20k</i>
			\$ 150.00 <i>40k</i>
			\$ 1,400.00 <i>600k</i>
TOTAL:			\$ 31,349.10
9% GST:			\$ 2,821.42
GRAND TOTAL:			\$ 34,170.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____

SPECIAL NETT
BODY SEALANT

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGE PARTS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO REMOVE & REFIT SPORT RIMS
TO SPRAY PAINTING ON THE AFFECTED AREA

35643-20

KBS Motorsports Pte Ltd
160 SIN MING DRIVE, #06-03
SIN MING AUTOCITY
t 6451 5333 f 6452 5333
COMPANY REG. NO.: 200504627K

KBS Motorsports Pte Ltd



YOUR REF.: SGH6194L

OUR REF.: SKA3511L

TO: SOMPO INSURANCE

CC: Claims Services Department

FAX:

DATE: 3/1/2025
FROM: Lee Shirley
FAX: 6452 5333
CONTACT: 8686 5188
MAKE & MODEL: PORSCHE 911
CARRERA 3.6 A
CHASSIS NO.: WP0ZZZ99ZAS700139
ENGINE NO.: MA102A01008
YEAR MADE: 2011
ACCIDENT DATE: 24 December 2024

SUPPLEMENTARY FOR VEHICLE NO.: SKA3511L

NO.	DESCRIPTION	QTY.	LIST PRICE	
1	FRONT FENDER SIGNAL LAMP LH	1	\$	<i>m/cm</i> 105.00 ✓
2	FRONT HEADLAMP MOUNTING LH <i>368</i>	1	\$	<i>R</i> 695.00 ✓
3	FRONT COOLANT RADIATOR LH	1	\$	<i>hous cm</i> 1,185.00 ✓
4	FRONT COOLANT RADIATOR AIR GUIDE LH <i>620</i>	1	\$	<i>cm</i> 750.00 ✓
5	FRONT COOLANT RADIATOR AIR DUCT LH	1	\$	<i>cm</i> 585.00 ✓
6	FRONT FENDER BRACE LH	1	\$	<i>R</i> 485.00 ✓
7	FRONT FENDER LINER FRONT LH <i>312.80</i>	1	\$	<i>cm</i> 485.00 ✓
8	FRONT FENDER LINER CLIP	6	\$	<i>cm</i> 66.00 ✓
9	FRONT BUMPER RETAINING STRIP LH	1	\$	<i>cm</i> 88.00 ✓
10	FRONT BUMPER RETAINING BRACKET LH	1	\$	<i>cm</i> 105.00 ✓
TOTAL:			\$	4,549.00
LESS 10%:			\$	(454.90)
PARTS TOTAL:			\$	4,094.10

SPECIAL NETT

AIRCON COOLANT 1 \$ *ne* 80.00 *4650*

LABOUR

TO REMOVE & INSTALL AIRCON COMPONENT INCLUDING CHARGE UP GAS \$ *1000* 120.00

TOTAL: \$ 4,294.10
9% GST: \$ 386.47
GRAND TOTAL: \$ 4,680.57