

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chu, Hui Yen

Date: 30 Dec 2024

Preliminary Advice

Vehicle No	: SFT9117L	Accident Date	: 23/12/2024
Make	: AUDI Q3	Policy No.	: 2070145666
Assignment Date	: 26/12/2024	Excess	: S\$800.00
Date of Inspection	: 27/12/2024	Est. Duration of Repair	: 8
Inspection At	: 24 BENOI SECTOR		
	REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,565.00
Revised Amount	:S\$	27,674.00
Check Items (Estimated)	:S\$	13,191.00
Total	:S\$	40,865.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	46,983.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,017.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.