

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURAI		Ref:	CS/LIP24070037/Uvh3	
	ONE RAFFLES QUAY #25-01 NORTH TOWER		Date:	02/07/2024	
	SINGAPORE 0485	83	Code:	LIP	
4		Policy Particulars :- THIRD PARTY CLAIM			
1.	Insured Veh.	SMH 7117E	Veh. Inspected	SMK 7040B	
	Policy No.	-	Coverage	0	
	Claim No.	- AVS24/2017	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	02/07/2024	
2.	Assign From		le Details	02/07/2024	
۷.	Make & Model	HONDA VEZEL HYBRID (A)	C.C	1496	
	Engine No.	LEB6744969	Year of Reg.	22/04/2019	
	Chassis No.	RU31324956	Colour	SILVER	
	Odometer	198840 KM	Steering	DAMAGED	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM	General		
2		Conditions of Tyres			
3.	I	Size	Make	Balance (mm)	
	R/H Front Tyre	225/55R17	PIRELLI	6	
	L/H Front Tyre	225/55R17	PIRELLI	6	
	R/H Rear Tyre	225/55R17	PIRELLI	6	
	L/H Rear Tyre	225/55R17	PIRELLI	6	
4.		11.2.2	on of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION, N/S BODY AND FRONT UNDER CARRIAGE AFFECTED.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	28/06/2024	Inspection Date	03/07/2024	
	Survey held at	vey held at FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840			
5a.	Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days