

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

Reg. No: 201538764H

CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	27/6/2024
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
<i>Hui Rong</i>	
VEHICLE DETAILS	
VEHICLE NO:	GP93P
MAKE & MODEL:	TOYOTA HIACE DX 2.8 AUTO
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	27 June, 2024
TIME:	0825HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT CORNER PANEL RH <i>Dented</i>	1	\$ 190.00	\$ 190.00
TOTAL PRICE				\$ 190.00
LESS 25%				\$ 47.50
SUB TOTAL PRICE				\$ 142.50

190
142.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 200.00	\$ 200.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 200.00	\$ 200.00
TOTAL			\$ 400.00	

200

ESTIMATE REPORT

TOTAL PARTS COST	\$	142.50
TOTAL LABOUR COST	\$	400.00
TOTAL REPAIR COST	\$	542.50

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adam Cj
P/P 04/07/24
01 Day.

Total: 342.50.