

Date : 27/12/2024
Vehicle No: SMS7687T
Model: TOYOTA CAMRY HYBRID 2.5
Chassis: JTNB23HKX03055818-2019
Reg.Year: 2020
Policy No: D23MPCM000397_1
Date of Accident: 25/12/2024
Estimator: TING AN

TO MOTOR CLAIM DEPT
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04/05/06-02 IOB BUILDING
SINGAPORE 049711

Not withash
Runny B4 pain
Ex @ 1500h
9 days

817,927.50

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		Ry \$500.00
2	FRONT BONNET HINGE LH	1		DIT \$45.00
3	FRONT BONNET HINGE RH	1		R1 \$45.00
4	FRONT BONNET STRUT LH	1		Pr \$130.00
5	FRONT BONNET STRUT RH	1		Ru \$130.00
6	FRONT BONNET INSULATOR	1		CM \$200.00
7	FRONT BONNET LOCK	1		Tn \$75.00
8	FRONT UPPER GRILLE ASSEMBLY	1		CM \$380.00
9	FRONT HEADLAMP RH	1		Bu \$980.00
10	FRONT BUMPER	1		Tn \$300.00
11	FRONT BUMPER SIDE BRACKET RH	1		CM \$50.00
12	FRONT BUMPER LOWER GRILLE	1		CM \$300.00
13	FRONT BUMPER UNDER COVER	1		DIT \$220.00
14	FRONT BUMPER REINFORCEMENT	1		Ry \$175.00
15	FRONT BUMPER ABSORBER FOAM	1		CM \$60.00
16	FRONT WIPER WASHER TANK	1		Bru \$90.00
17	FRONT SUPPORT PANEL	1	\$690	Ry \$525.00
18	FRONT SUPPORT PANEL UPPER COVER	1		Nd \$150.00
19	FRONT FENDER RH	1		Ry \$360.00
20	FRONT FENDER "HYBRID" EMBLEM	1		Ru \$40.00
21	FRONT FENDER INNER SHIELD RH	1		CM \$100.00
22	FRONT FENDER AIR GUIDE RH	1		CM \$85.00
23	FRONT FENDER INNER PANEL RH	1		R1 \$450.00
24	FRONT FENDER OUTER PANEL RH	1	\$550	Ry \$450.00
25	FRONT RIM RH	1		R \$1,900.00
26	FRONT ABSORBER RH	1	Ry \$95	\$750.00
27	FRONT LOWER ARM RH	1		DIT \$250.00
28	FRONT KNUCKLE ARM RH	1		R1 \$260.00
29	FRONT WHEEL BEARING RH	1		Ru \$300.00
30	FRONT STABILISER LINKAGE RH	1		DIT \$85.00
31	FRONT TIE ROD END RH	1		R1 \$85.00

Date : 27/12/2024
 Vehicle No: SMS7687T
 Model: TOYOTA CAMRY HYBRID 2.5
 Chassis: JTNB23HKX03055818-2019
 Reg.Year: 2020
 Policy No: D23MPCM000397_1
 Date of Accident: 25/12/2024

TO MOTOR CLAIM DEPT
 INDIA INTERNATIONAL INSURANCE
 64 CECIL STREET
 #04/05/06-02 IOB BUILDING
 SINGAPORE 049711

32	FRONT STEERING RACK	1	B/I Jn	\$2,280.00	✓
33	FRONT CROSSMEMBER	1	Ry	\$1,200.00	✓
34	FRONT DOOR RH	1	B/I	\$700.00	✓
35	FRONT DOOR WEATHERSTRIP RH	1	Rn	\$130.00	X
36	SIDE SKIRT RH	1	Bn	\$400.00	✓
SUB TOTAL				\$14,180.00	\$11760
COST +10%				\$1,418.00	
PARTS TOTAL				\$15,598.00	\$12936

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET INSULATOR CLIPS	1		Mn \$50.00	✓
2	FRONT BUMPER CLIPS	1		Mn \$50.00	✓
3	FRONT GRILLE CLIPS	1		Mn \$40.00	✓
4	FRONT NUMBER PLATE & HOLDER	1		M/Y \$50.00	450
5	FRONT TYRE RH	1	\$90 Rn	\$300.00	3000
6	FRONT FENDER INNER SHIELD CLIPS RH	1		Mn \$40.00	✓
7	FRONT DOOR INNER TRIM BOARD CLIPS	1		Mn \$50.00	720
S/N TOTAL				\$580.00	\$335

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

1200/ \$2,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT FENDER PANEL RH, FRONT DOOR RH, SIDE SKIRT RH & ETC.

1200/ \$1,500.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MEACHNISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

\$120.00 60/

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT WHEEL BEARING RH, FRONT LOWER ARM RH, FRONT STEERING

\$500.00 200/

Date : 27/12/2024
Vehicle No: SMS7687T
Model: TOYOTA CAMRY HYBRID 2.5
Chassis: JTNB23HKX03055818-2019
Reg.Year: 2020
Policy No: D23MPCM000397_1
Date of Accident: 25/12/2024
RACK, FRONT CROSSMEMBER & ETC.

TO MOTOR CLAIM DEPT
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04/05/06-02 IOB BUILDING
SINGAPORE 049711

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 ✓

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$120 ✓ \$300.00 ?

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$150.00 2d

LABOUR TOTAL \$4,650.00 \$2880

TING AN

TOTAL

\$20,828.00

Date : 02/01/2025
 Vehicle No: SMS7687T
 Model: TOYOTA CAMRY HYBRID 2.5
 Chassis: JTNB23HKX03055818-2019
 Reg.Year: 2020
 Policy No: D23MPCM000397_1
 Date of Accident: 25/12/2024

TO MOTOR CLAIM DEPT
 INDIA INTERNATIONAL INSURANCE
 64 CECIL STREET
 #04/05/06-02 IOB BUILDING
 SINGAPORE 049711

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DRIVESHAFT RH	1		BT \$780.00 ✓
2	FRONT BALL JOINT RH	1		A1 \$90.00 ✓
3	CROSSMEMBER MOUNTING	4	\$75.00	MC \$300.00 ✓
4	HEADLAMP BALLAST RH	1		CM \$360.00 ✓
5	FRONT BUZZER	1		Red \$85.00 ✓
SUB TOTAL				\$1,615.00
COST +10%				\$161.50
PARTS TOTAL				\$1,776.50 ✓

TOTAL \$1,776.50

Finalise:

Parts: \$12936

Supp: \$1776.50

Nett: \$335

Labour: \$2880

P/P: \$17927.50