

Date : 27/12/2024
 Vehicle No: SMS7687T
 Model: TOYOTA CAMRY HYBRID 2.5
 Chassis: JTNB23HKX03055818-2019
 Reg.Year: 2020
 Policy No: D23MPCM000397_1

TO MOTOR CLAIM DEPT
 INDIA INTERNATIONAL INSURANCE
 64 CECIL STREET
 #04/05/06-02 IOB BUILDING
 SINGAPORE 049711

Date of Accident: 25/12/2024

32	FRONT STEERING RACK	1	By Jn	\$2,280.00	✓
33	FRONT CROSSMEMBER	1	By	\$1,200.00	✓
34	FRONT DOOR RH	1	By	\$700.00	✓
35	FRONT DOOR WEATHERSTRIP RH	1	By	\$130.00	X
36	SIDE SKIRT RH	1	By	\$400.00	✓

SUB TOTAL	\$14,180.00	\$11760
COST +10%	\$1,418.00	
PARTS TOTAL	\$15,598.00	\$12936

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET INSULATOR CLIPS	1		By	\$50.00 ✓
2	FRONT BUMPER CLIPS	1		By	\$50.00 ✓
3	FRONT GRILLE CLIPS	1		By	\$40.00 ✓
4	FRONT NUMBER PLATE & HOLDER	1		By	\$50.00 ✓
5	FRONT TYRE RH	1	\$90	By	\$300.00 30Wn
6	FRONT FENDER INNER SHIELD CLIPS RH	1		By	\$40.00 ✓
7	FRONT DOOR INNER TRIM BOARD CLIPS	1		By	\$50.00 720
S/N TOTAL				\$580.00	\$335

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

1200
\$2,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT FENDER PANEL RH, FRONT DOOR RH, SIDE SKIRT RH & ETC.

1200
\$1,500.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MEACHNISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

\$120.00 600

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT WHEEL BEARING RH, FRONT LOWER ARM RH, FRONT STEERING

\$500.00 2000

Date : 27/12/2024
Vehicle No: SMS7687T
Model: TOYOTA CAMRY HYBRID 2.5
Chassis: JTNB23HKX03055818-2019
Reg.Year: 2020
Policy No: D23MPCM000397_1
Date of Accident: 25/12/2024
RACK, FRONT CROSSMEMBER & ETC.

TO MOTOR CLAIM DEPT
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04/05/06-02 IOB BUILDING
SINGAPORE 049711

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 ✓

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$120 ✓ \$300.00 ?

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$150.00 2d

LABOUR TOTAL \$4,650.00 \$2880

TING AN

TOTAL \$20,828.00

Date : 02/01/2025
 Vehicle No: SMS7687T
 Model: TOYOTA CAMRY HYBRID 2.5
 Chassis: JTNB23HKX03055818-2019
 Reg.Year: 2020
 Policy No: D23MPCM000397_1
 Date of Accident: 25/12/2024

TO MOTOR CLAIM DEPT
 INDIA INTERNATIONAL INSURANCE
 64 CECIL STREET
 #04/05/06-02 IOB BUILDING
 SINGAPORE 049711

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DRIVESHAFT RH	1		<i>BT</i> \$780.00
2	FRONT BALL JOINT RH	1		<i>A</i> \$90.00
3	CROSSMEMBER MOUNTING	4	\$75.00	<i>MC</i> \$300.00
4	HEADLAMP BALLAST RH	1		<i>CM</i> \$360.00
5	FRONT BUZZER	1		<i>Red</i> \$85.00
			SUB TOTAL	\$1,615.00
			COST +10%	\$161.50
			PARTS TOTAL	\$1,776.50

TOTAL	\$1,776.50
-------	------------

Finalise:

Parts: \$12936

Supp: \$1776.50

Nett: \$335

Labour: \$2880

P/P: \$17927.50