

ASS. REC. BY:

REF:

Smo/ CS/SMO24120419/KNP3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$39k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or NoLum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: PLU 834HYr Regn: 11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mazda 5c.c. 1998Colour M.D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading 144946

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6CW1071140127050

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: ArivoR: Finns 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 3 mmL/Bal. 9 mmL/Bal. 3 mmD.O.A. 18/12/24D.O.I. 30/12/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ Wkg unable to locate 2nd party

17/12 @ 2973.75 Cdn (Red. \$ 865, 227)

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0036416
Neo Yao Sheng

Page 1 of 2
Your ref. TP-SNK 114G Somp
Job No. 74898
Our ref. 24.12.18
Payment
Date 23/12/2024

Attn

Vehicle No ... : SLU 834H
Vehicle Model : Mazda 5
Accident on ... : 18/12/2024

\$ 2973.75

Not withash
Remy Bypain
Edan

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	380.00		Bu 380.00 ✓
1.00	Pc	Rear bumper reinforcement	100.00		R 100.00 X
1.00	Pc	Rear Mazda logo emblem	35.00		M 35.00 ✓
1.00	Pc	Rear Mazda emblem	22.00		M 22.00 ✓
1.00	Pc	Rear 5 emblem	18.00		M 18.00 ✓
1.00	Pc	Rear SKYACTIV emblem	38.00		M 38.00 ✓
1.00	Pc	Rear windscreen upper moulding	38.00		M 38.00 ✓
1.00	Pc	Tailgate	680.00		R 680.00 ✓
1.00	Pc	Tailgate garnish	200.00		R 200.00 ✓
Total amount of parts supplied-S\$1,511.00					
1.00		25% of parts supplied:	377.75		377.75
Special nett item:					
1.00	Set	Rear reverse camera+installation	250.00		R 250.00 X
1.00	Set	Rear reversing sensor+installation	200.00		R 200.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0036416
Neo Yao Sheng

Page 2 of 2
Your ref. TP-SNK 114G Somp
Job No. 74898
Our ref 24.12.18
Payment
Date 23/12/2024

Attn

Vehicle No ... : SLU 834H
Vehicle Model : Mazda 5
Accident on ... : 18/12/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Labour & Misc:					
1.00		To dismantle+refix rear windscreen	160.00		160.00 120/-
1.00		To supply sealant	40.00		40.00 ✓
1.00		To knock dents on rear end panel and renew parts	600.00		600.00 400/-
1.00		To spray paint	700.00		700.00 450/-
Sub-Total					3,838.75
GST 9.00%					345.49
Total					S\$ 4,184.24

本公司拥有最先进的 CARLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CARLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Tokio Marine Insurance Singapore Ltd.

(Company Reg. No: 192300014M) (GST Reg No: M2-0000023-4)

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmis@tokiomarine.com.sg W: www.tokiomarine.com

A member of the
Tokio Marine Group



TOKIO MARINE
INSURANCE GROUP

Certificate of Insurance

FORM MX1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: MZD08743 (Private Car)

1. Index Mark and Registration Number of Vehicle

SLU834H

Chassis No.: JM6CW1071H0127050

2. Name of Policyholder

NEO YAO SHENG

3. Effective date of the Commencement of Insurance for the purposes of the Act

22/11/2024 (00:00:00)

4. Date of Expiry of Insurance

21/11/2025

5. Persons or Class of Persons entitled to drive*

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost/destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account No: 0751DDA

Insurance Plan: Comprehensive Approved Workshop Plan

Limit for total loss or theft: Prevailing Market Value

Policy Excess:	Own Damage Claims	SGD 800.00	(Original Excess : SGD 800.00)
	Additional Excess for Unnamed Driver(s)	SGD 500.00	
	Additional Excess for Young or Inexperienced Driver(s)	SGD 3,500.00	
	WindScreen Excess	SGD 100.00	

Financial Interest: NIL

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorised Signature

INSURER ENQUIRY

**Find
insurer**

Vehicle reg. no.

SNK114G

Date of Accident

18/12/2024 

Reset

% **RESULT & RECEIPT**

TP Insurer Enquiry

Insurance **Sompo Insurance Singapore P...**Period of Insurance **19/07/2024 - 18/07/2025**Requested By **Jenny Lim (Lai Huat (Meng Ke...**Requested Date **19/12/2024 10:51****Payment details**Request Amount: **S\$2**GST Amount: **S\$0.18**Total Amount Due (GST Inclusive): **S\$2.18****General Insurance Association**

Records Management Centre

GST Registration No: **M400017735**