

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24120423/Avh3e2(N)	
	75 BRAS BASAH FINCOME CENTRE		Date:	12/03/2025		
	ATTN: RAJESWAR	RY		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBA 8833G	Veh. Inspecte	d	SNT 6878Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1309156-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		26/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA NOAH HYBRID	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2024	
	Chassis No.	ZWR900183009	Colour		BLACK	
	Odometer	8474 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	BRIDGESTONE		6 mm	
	L/H Front Tyre	205/60 R16	BRIDGESTONE		6 mm	
	R/H Rear Tyre	205/60 R16	BRIDGESTONE		6 mm	
	L/H Rear Tyre	205/60 R16	BRIDGESTONE		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
	DAWAGES SEE DI	ETAILO.			1.0	
5.	General Information					
J.	Accident Date 19/12/2024 Inspect Date / Time 27/12/2024 (11:48 AM)					
	Survey held at	KT MOTORWERK	mopost Bato /			
	Currey nera ar	3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		6 Workii	ng Days	