

PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315




Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 7 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M




PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M




PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M



PHOTOGRAPHS FOR VEHICLE NO. : SMC 4647M

