

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/12/2024
Vehicle Reg. No.:	<b>SHC3316J</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 HATCHBACK(AT)(2WD) (A)	Vehicle Reg. Date:	31/05/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2C26673	Chassis No:	JTDKB3FU003081224
Odometer:	472254 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	1,354.44
Miscellaneous Items	12.00
Labour	1,060.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,426.44</b>
<b>+ GST 9.00% (S\$)</b>	<b>218.38</b>
<b>Nett Amount (S\$)</b>	<b>2,644.82</b>

**This claim is handled by: CHIANG LIAT CHOON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 28 Dec 2024)

**Parts:** 144      TOYOTA PRIUS TAXI 1.8 HATCHBACK(AT)(2WD) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3316J/28/12/2024 09:54

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>x R</i>	25.00	0.00	*503.04 FL
2	1		*REAR BUMPER LOWER COVER <i>ruj</i>	25.00	0.00	*654.96 FL /
3	1		*REAR BUMPER REINFORCEMENT <i>x nn</i>	25.00	0.00	*378.32 FL
4	10		*REAR BUMPER CLIP <i>x nn</i>	25.00	0.00	*22.00 FL
5	1		*REAR BUMPER MAT <i>x nn</i>	0	0.00	*50.00 FS
6	1		*REAR REVERSE SENSOR <i>x nn</i>	0	0.00	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,744.02</b>
<b>- List Item Discount on L Items (S\$)</b>	<b>389.58</b>
<b>Total Parts (S\$)</b>	<b>1,354.44</b>

ComfortDelGro Engineering Pte Ltd/SHC3316J/28/12/2024 09:54. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

491.22

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	12.00 /
<b>Sub Total (\$)</b>			<b>12.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	380 700.00
2	SPRAY PAINTING	New	280 300.00
3	REMOVE/REFIX REVERSE SENSOR.	New	20 60.00
<b>Gross Labour Cost (\$)</b>			<b>1,060.00</b>

ComfortDelGro Engineering Pte Ltd/SHC3316J/28/12/2024 09:54. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1,183.22

L/S - 946.57  
= 950

*Steve CLKK*  
*30/12/24, 3:00pm*  
*W h*  
*L/S*  
*by Mr sy*  
*2 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: