



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24120441/Knh3e2(N) Date: 05/02/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 350E	Veh. Inspected	SNL 7612J
	Policy No.		Coverage (\$)	0.00
	Claim No.	IVS25/0023	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	27/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA (A)	c.c	1490
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JTDBBBA3X0L000867	Colour	GREY
	Odometer	59474 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	GOODYEAR	8 mm
	L/H Front Tyre	185/65 R15	GOODYEAR	8 mm
	R/H Rear Tyre	185/65 R15	GOODYEAR	8 mm
	L/H Rear Tyre	185/65 R15	GOODYEAR	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/12/2024	Inspection Date	30/12/2024
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)REGISTRATION DATE: 31 JUL 2023 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	