



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24120442/Uvh3e2(N) Date: 09/01/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKB 30Y	Veh. Inspected	SMA 4859D
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS25/0024	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	27/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	KMHD841CMJU685425	Colour	BLACK
	Odometer	92447 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
	L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/12/2024	Inspection Date	30/12/2024
	Survey held at	CARSMITH PTE LTD 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		
5a. Remarks				
	A)REGISTRATION DATE: 11 JUN 2018 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	