

MCGAP WORKSHOP
60, ALAN LAM HUAT CARROS CENTRE
#05-68 S(737869)
HP:97816380

*Not Notified
11 days & 16000
Penny After Paint
4 days*

TO: HSBC

DATE : 4/11/2024

ATTENTION: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

VEHICLE DETAIL

VEHICLE NO: SMK4185L

MODEL: HONDA SHUTTLE

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

S/N	DESCRIPTION	QTY	UNIT LIST	TOTAL LIST
1	FRONT DOOR RH	1	\$1,250.00	\$1,250.00
2	REAR DOOR RH	1	\$950.00	\$950.00
3	REAR RETAINER RH	1	\$60.00	\$60.00
4	REAR FENDER RH	1	\$450.00	\$450.00
5	FRONT FENDER RH	1	\$180.00	\$180.00
6	SIDE SKIRT	1	\$120.00	\$120.00
7	RIM	1	\$350.00	\$350.00
8	FRONT DOOR HANDLE	1	\$680.00	\$680.00
9	REAR DOOR HANDLE	1	\$420.00	\$420.00
10	FRONT BUMPER	1	\$550.00	\$550.00
11	FRONT FENDER RH			
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				

PRICE (\$1050.50) nd/cra

208

TOTAL PRICE \$5,010.00
LESS 10% -\$501.00
SUB TOTAL PRICE \$4,509.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL ITEMS PART

S/N	DESCRIPTION	QTY	UNIT LIST	TOTAL LIST
1	FRONT DOOR HANDLE CARBON	<i>nn</i> 1	240	\$240.00
2	REAR DOOR HANDLE CANBON	<i>nn</i> 1	240	\$240.00
3				
4				
5				
6				
7				
8				
9				
10				

TOTAL PRICE

\$480.00

S/N	DESCRIPTION	QTY	UNIT LIST	TOTAL LIST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	700	\$700.00
2	TO SPRAY PAINT AFFECTED AREA	1	900	\$900.00
3	ALIGNMENT CHECK	1	80	<i>nn</i> \$80.00
4	WIRING CHECK	1	60	\$60.00
5				\$0.00
6				\$0.00
7				\$0.00
8				\$0.00
9				\$0.00
10				\$0.00
11				\$0.00

TOTAL PRICE

\$1,740.00

FINAL AMOUNT COST:

ATTN BY SURVEYOR: