

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24120458/Aqh3m4(N)	
	75 BRAS BASAH R INCOME CENTRES		Date:	15/04/2025		
	ATTN: MARCUS XI	AO		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKZ 1040K	Veh. Inspected	k	SNM 4167S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1310158-001	Excess (\$)		0.00	
	Assign From	JULIET KOH	Assign Date		30/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ C180 COUPE	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	WDD2053402F738214	Colour		BLACK	
	Odometer	111765 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/35R19	MICHELIN		6 mm	
	L/H Front Tyre	245/35R19	MICHELIN		6 mm	
	R/H Rear Tyre	245/35R19	MICHELIN		6 mm	
	L/H Rear Tyre	245/35R19	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DE	ETAILS.				
5.	General Information					
	Accident Date	24/12/2024	Inspect Date /	Time	06/01/2025 ( 12:27 PM )	
	Survey held at	ONE GARAGE PTE LTD				
		8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					