



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 ATTN: JIA YI			Ref: CS/SMO24120473/Avp3e2(N) Date: 26/02/2025 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 4322J	Veh. Inspected	GBJ 4178T
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2404171/JYC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	31/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	FIAT FIORINO	c.c	1248
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	ZFA22500006H38902	Colour	WHITE
	Odometer	99651 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	MAXIMUM	6 mm
	L/H Front Tyre	185/65 R15	MAXIMUM	6 mm
	R/H Rear Tyre	185/65 R15	MAXIMUM	6 mm
	L/H Rear Tyre	185/65 R15	MAXIMUM	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/12/2024	Inspection Date	31/12/2024
	Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	