



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		Mr Yiong Hoi Liong 237 Tampines Street 21 #08-563 Singapore 520237 Mobile: 96882755		
			Document No. 0				
			Document Date 10/07/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P3	17/03/2021	SKL8691J	0	23034	77/DS/SKL8691J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTMV43FV00D516699		M20AV268719	60	Cheng Wei Ting	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES ACC DATE:08/07/2023 TP VEH:SFJ3139R TP INS:LONPAC INS DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00	
2	B	BP-LAB2 TO CHECK WIRING AND CARRY OUT WATER LEAK TEST				134.64	
3	B	BP-LAB2 TO DRILL HOLES AND INSTALL REAR BUMPER S ENSOR				198.00	
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
5	B	BP-MECH2 TO CONDUCT REAR BLINDSPOT SENSOR ADJUSTMENT				198.00	
6	B	BP-LAB2 TO REMOVE AND REINSTALL TAILGATE'S COMPONENT,MECHANISM AND REVERSE CAMERA TO NEW TAILGATE				792.00	
7	B	BP-WS2 RENEW REAR SCREEN GLASS				594.00	
8	S	BP-SUBLET TO SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM				480.00	
9	B	BP-LAB2 TO REMOVE AND INSTALL REAR INTERIOR UPHOLSTERY TO ENABLE FOR THE REPAIR JOB				396.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	Mr Yiong Hoi Liong 237 Tampines Street 21 #08-563 Singapore 520237 Mobile: 96882755
	Document No. 0	
	Document Date 10/07/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P3	17/03/2021	SKL8691J	0	23034	77/DS/SKL8691J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTMY43FV00D516699	M20AV268719	60	Cheng Wei Ting	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				366.36
11	B	BP-LAB2 TO REPAIR AND REPLACE ON ACCIDENT AFFECTED AREA				4752.00
12	B	BP-RES2 TO SPRAY PAINTING ON ACCIDENT AFFECTED AREA				3936.00
13	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
14	B	BP-MECH2 TO REPLACE AND REALIGN ON EXHAUST PIPE				396.00
15	1	T52159-42230 COVER, RR BUMPER	1.00	423.10		423.10
16	2	S52161-0K040 PIECE, RR BUMPER	10.00	5.30		53.00
17	3	T75392-35220 RETAINER, OUTSIDE	6.00	5.20		31.20
18	4	T52453-42040 B0 GUARD, RR BUMPER,	1.00	836.20		836.20
19	5	T75392-35220 RETAINER, OUTSIDE	4.00	5.20		20.80
20	6	T90189-06228 GROMMET, SCREW	2.00	2.80		5.60
21	7	T52599-68030 STOPPER, RR BUMPER,	2.00	5.70		11.40
22	8	T52562-42060 RETAINER, RR BUMPER,	1.00	133.60		133.60
23	9	T52563-42050 RETAINER, RR BUMPER,	1.00	133.60		133.60
24	0	T52155-42050 SUPPORT, RR BUMPER	1.00	100.20		100.20
25	1	T52156-42050 SUPPORT, RR BUMPER	1.00	100.20		100.20
26	2	T52591-42100 SEAL, RR BUMPER	1.00	84.40		84.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		Mr Yiong Hoi Liong 237 Tampines Street 21 #08-563 Singapore 520237 Mobile: 96882755			
			Document No. 0					
			Document Date 10/07/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MXAA52R	ANXGBW P3	17/03/2021	SKL8691J	0	23034	77/DS/SKL8691J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTMV43FV00D516699		M20AV268719	60	Cheng Wei Ting	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
27	3	T52592-42100 SEAL, RR BUMPER			1.00	98.90		98.90
28	4	T52023-42060 REINFORCEMENT			1.00	485.60		485.60
29	5	T52161-42944 PIECE, RR BUMPER, RH			1.00	436.80		436.80
30	6	T52462-42030 PAD, RR BUMPER, RH			1.00	11.90		11.90
31	7	T52462-42020 PAD, RR BUMPER, RH			2.00	11.90		23.80
32	8	T76828-60030 RETAINER, BACK DOOR			2.00	4.20		8.40
33	9	T52162-42944 PIECE, RR BUMPER, LH			1.00	436.80		436.80
34	0	T52463-42020 PAD, RR BUMPER, LH			1.00	11.90		11.90
35	1	T52463-42010 PAD, RR BUMPER, LH			1.00	11.90		11.90
36	2	T76829-60020 RETAINER, BACK DOOR			2.00	1.90		3.80
37	3	SPC507-42001 RAV4 BACK SENSOR RES			1.00	221.80		221.80
38	4	T891B1-42030 BRACKET, KICK DOOR			1.00	189.40		189.40
39	5	T891B2-0W050 SENSOR, KICK DOOR			1.00	710.70		710.70
40	6	T89747-30040 BUZZER, WIRELESS			1.00	173.50		173.50
41	7	T58307-42050 PANEL SUB-ASSY, BODY			1.00	944.00		944.00
42	8	T62940-42020 DUCT ASSY, QUARTER			1.00	175.90		175.90
43	9	T67005-42650 PANEL SUB-ASSY, BACK			1.00	2772.40		2772.40
44	0	T67881-42070 WEATHERSTRIP, BACK			1.00	430.30		430.30
45	1	T67372-42020 WEIGHT, BACK DOOR			1.00	146.40		146.40
46	2	T67816-42020 SHEET, BACK DOOR			1.00	120.40		120.40
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	Mr Yiong Hoi Liong 237 Tampines Street 21 #08-563 Singapore 520237 Mobile: 96882755
	Document No. 0	
	Document Date 10/07/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P3	17/03/2021	SKL8691J	0	23034	77/DS/SKL8691J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTMY43FV00D516699	M20AV268719	60	Cheng Wei Ting	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
47	3	T68105-42300 GLASS SUB-ASSY, BACK	1.00	1580.70		1580.70
48	4	T62785-60030 SPACER, QUARTER	2.00	7.60		15.20
49	5	T76802-42140 GARNISH SUB-ASSY,	1.00	307.10		307.10
50	6	T76801-42904 GARNISH S/A, BACK	1.00	516.10		516.10
51	7	T76826-42140 RETAINER, BACK DOOR	1.00	11.10		11.10
52	8	T76827-42050 RETAINER, BACK DOOR	1.00	11.10		11.10
53	9	T76825-42040 PROTECTOR, BACK DOOR	1.00	33.10		33.10
54	0	T68810-42100 HINGE ASSY, BACK	2.00	91.60		183.20
55	1	T69350-42101 LOCK ASSY, BACK DOOR	1.00	1016.30		1016.30
56	2	T69430-48030 STRIKER ASSY, BACK	1.00	52.50		52.50
57	3	T68910-42060 UNIT ASSY, POWER	1.00	1484.80		1484.80
58	4	T68920-42020 UNIT ASSY, POWER	1.00	1484.80		1484.80
59	5	T84270-42040 SENSOR ASSY, POWER	1.00	1126.00		1126.00
60	6	T84280-42040 SENSOR ASSY, POWER	1.00	1126.00		1126.00
61	7	T90975-02070 EMBLEM, SYMBOL	1.00	73.60		73.60
62	8	T75431-42180 EMBLEM, BACK DOOR,	1.00	70.00		70.00
63	9	T75431-42190 EMBLEM, BACK DOOR,	1.00	70.00		70.00
64	0	T75605-42160 MOULDING SUB-ASSY,	1.00	142.80		142.80
65	1	T75606-42150 MOULDING SUB-ASSY,	1.00	142.80		142.80
66	2	T81581-42092 LENS & BODY, RR	1.00	595.60		595.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia				S1000007 / ICLPI1		Mr Yiong Hoi Liong 237 Tampines Street 21 #08-563 Singapore 520237 Mobile: 96882755			
				Document No. 0					
				Document Date 10/07/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	MXAA52R	ANXGBW P3	17/03/2021	SKL8691J	0	23034	77/DS/SKL8691J		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTMV43FV00D516699		M20AV268719	60	Cheng Wei Ting	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
67	3	T81591-42121 LENS & BODY, RR				1.00	310.50		310.50
68	4	T81551-42230 LENS & BODY, RR				1.00	656.20		656.20
69	5	T81561-42230 LENS & BODY, RR				1.00	656.20		656.20
70	6	T81497-42010 COVER, RR				1.00	56.90		56.90
71	7	T81498-42010 COVER, RR				1.00	56.90		56.90
72	8	T81910-48012 REFLECTOR ASSY,				1.00	77.20		77.20
73	9	T81920-48012 REFLECTOR ASSY,				1.00	77.20		77.20
74	0	T17408-25041 BAFFLE SUB-ASSY,				2.00	200.20		400.40
75	1	T17430-25221 PIPE ASSY, EXHAUST				1.00	2165.60		2165.60
76	2	L17565-22040 SUPPORT, EXHAUST				1.00	63.00		63.00
77	3	T17565-28010 SUPPORT, EXHAUST				1.00	63.00		63.00
78	4	T17565-28010 SUPPORT, EXHAUST				1.00	63.00		63.00
79	5	T17577-25010 BRACKET, EXHAUST				1.00	70.80		70.80
80	6	T17576-25020 BRACKET, EXHAUST				1.00	70.80		70.80
81	7	T58387-42130 C0 PLATE, RR FLOOR				1.00	309.30		309.30
For & on behalf of		Customer's Signature		Charge Summary			Total		
Borneo Motors (Singapore) Pte Ltd							37,108.70		
		Please acknowledge receipt of vehicle		Parts 24,487.70			GST 8.00% 2,968.70		
				Labour 11,694.64					
				Sublet 926.36					
				Lubrication/Fluid 0.00			Less 0.00		
				Others 0.00			Amount Due 40,077.40		

Customer Copy