

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBF9977Y210113

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte LtdAddress Motor Claims Department78 Shenton Way #07-16AIG BuildingSingapore 079120

Date:

15-01-21Vehicle No: GBF9977YModel/Make: Fiat Doblo CargoMaxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front View Door View Mirror <i>LH</i>	\$ 1,142.80	
2	Side Mirror Cover <i>LH</i>	\$ 212.00	
3	Door Glass <i>LH</i>	\$ 456.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 250.00	- 100
	To putty & spray painting & including touch up paint on accident affected are	\$ 150.00	- 50

Total Parts & Labour of estimate for damaged vehicle

\$ 2,210.80

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not authorized
1/3 \$ 1250/
18/1/21
whenever
2 days

WHL: Jasper

2,1598.8
102
1438.92
1688.92
202
1211

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: