

ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PNN 94915 Yr Regn: 12, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A) WagonMake: Toy Vaux C.C. 1797Colour M. P. White A/C: Insured / Std / Nil / NASp. Reading 42517 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: ZWR90 0135298Gen. Cond: Good / Fair / Poor / BurntSteering: Inoper / Jammed / Leaked / Burnt orBrake: Inoper / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUK /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 7 mmL/Bal. 5 mm L/Bal. 7 mmD.O.A. 29/6/24 D.O.I. 3/7/2024Survey held at ✓Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

Transportation

2)

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. \$ _____

☐ : Interview (\$ _____)

Fees

☐ : Tech Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI DRIFT RD # 03-76 SYNERGY @ K11 8417809

DATE 02/07/2024
VEHICLE SNN9491S
MAKE/MODEL TOYOTA / VOXY
CHASSIS NO ZWR90-0135298
MILLAGE 42517KM
TYRE SIZE 205/55/R17
DOA 26/06/2024

LIST ITEM

01 PC	TAIL GATE	Rs	2,281.24	✓
02 PC	TAIL GATE HINGES @ \$112.74	R	225.48	X
02 PC	TAIL GATE ABSORBER @ \$335.99	Sn	671.98	X
01 PC	TAIL GATE TRIMBOARD	Sn	747.14	✓
01 PC	TAIL GATE OUTER GARNISH	ms	809.06	✓
02 PC	TAIL GATE OUTER LAMP @ \$1127.36	cm	2,254.72	✓
01 PC	TAIL GATE OUTER SWITCH	S	365.02	?
01 PC	TAIL GATE EMBLEM (HYBRID)	ms	77.36	✓
01 PC	TAIL GATE EMBLEM (LOGO)	ms	109.21	✓
01 PC	TAIL GATE EMBLEM (VOXY)	ms	182.34	✓
01 PC	TAIL GATE INNER LOCK	ms	658.75	✓
01 PC	TAIL GATE CATCH LOCK	Sn	46.82	X
01 PC	TAIL GATE INNER HANDLE	Sn	63.20	X
02 PC	TAIL GATE INNER STOPPER @ \$40.67	R	81.34	X
02 PC	TAIL GATE NUMBER PLATE LAMP @ \$171.24	S	342.48	?
02 PC	TAIL LAMP @ \$1295.36	ms	2,590.72	✓
02 PC	TAIL LAMP BRACKET @ \$65.31	S	130.62	✓
01 PC	REAR BUMPER	Rs	2,449.24	✓
01 PC	REAR BUMPER UNDER COVER	ms	326.45	X
02 PC	REAR BUMPER SIDE RETAINER @ \$185.30	S	370.60	?
02 PC	REAR BUMPER REFLECTOR @ \$117.14	cm	234.28	✓
02 PC	REAR BUMPER REFLECTOR COVER @ \$140.28	cm	280.56	✓
02 PC	REAR CORNER PANEL @ \$165.30	S	330.60	?
02 PC	REAR CORNER PANEL BRACKET @ \$144.50	S	289.00	?
01 PC	REAR END PANEL	Rs	642.20	✓
01 PC	REAR END PANEL TOP GANISH	ms	365.10	✓
01 PC	REAR SPARE TYRES PANEL	S	854.36	?
01 PC	REAR SPARE TYRES BOARD	cm	786.20	✓
02 PC	REAR INNER PANEL TRIM BOARD @ \$689.53	ms	1,397.06	✓
01 PC	REAR WEATHERSTRIP	S	406.73	?
01 PC	REAR TAIL GATE CAMERA	Sn	650.20	X
01 PC	REAR ANTENNA SENSOR	S	236.70	?
01 PC	REAR BUMPER HARNESS	S	229.87	?
01 PC	REAR WINDSCREEN	Sn	1,741.50	X
01 PC	REAR WINDSCREEN MOULDING	ms	320.45	✓
01 PC	REAR EXHAUST	R	645.47	X
03 PC	REAR EXHAUST RUBBER @ \$25.00	Sn	75.00	X
		S	24,269.05	

Special Net

2 PC	PARKING SENSOR @ \$220	ms	880.00	✓
10 PC	REAR TRIM BOARD CLIP @ \$8	ms	80.00	✓
01 PC	REAR WINDSCREEN SEALANT	S	100.00	40JA
01 PC	PHV STICKER	ms	25.00	X
06 PC	BUMPER CLIP @ \$8	ms	48.00	✓
		S	1,133.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,200.00	1900
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	800.00	✓
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	201
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	150.00	606
5. TO SUPPLY DIAGNOSTIC & REPROGRAMMING	\$	300.00	?
6. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$	300.00	1201
	\$	2,950.00	

LR Auto Consultants hence notify the Repairer of the following:

TOTAL PARTS
TOTAL SPECIAL NETT
TOTAL LABOUR
TOTAL COST OF REPAIR

Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
L1 Rep &
Resurvey After Paint
6 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	01/07/2024 11:10 (SGT)
Reported by	Actual Driver
Date of Accident	29/06/2024 10:20 (SGT)
Exact Location of Accident	ECP, Singapore
Additional Location Information	ALONG ECP EXPRESSWAY TOWARD CHANGI AIRPORT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNN9491S
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	SKYWAY MOTOR PTE LTD
Company Reg No	1XXXXX194N
Email Address	JAY@SKYWAY.COM.SG
Mobile Phone No	(Phone) +65-87211111
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Voxy
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1797

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2007019568

DRIVER

Name of Driver	LIM YEOW KIANG
NRIC No	SXXXX493H
Date Of Birth	02/03/1968
Occupation	Outdoor