



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070060/Uvp3
16 RAFFLES QUAY	Date:	29/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4450S	Veh. Inspected	SLR 1590U
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005769MFCT	Excess	\$0.00
Assign From	-	Assign Date	03/07/2024

2. Vehicle Details

Make & Model	HONDA FREED (A)	C.C	1496
Engine No.	L15B4254424	Year of Reg.	01/08/2017
Chassis No.	GB51033965	Colour	WHITE
Odometer	84064 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/65R15	DUNLOP	6
L/H Front Tyre	185/65R15	DUNLOP	6
R/H Rear Tyre	185/65R15	DUNLOP	6
L/H Rear Tyre	185/65R15	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/06/2024	Inspection Date	02/07/2024
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days