

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Wan, Haohui

Date: 03 Jul 2024

Preliminary Advice

Vehicle No	: SMC1230B	Accident Date	: 07/06/2024
Make	: AUDI Q3	Policy No.	: 1800075916
Assignment Date	: 13/06/2024	Excess	: S\$400.00
Date of Inspection	: 14/06/2024	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,000.00
Revised Amount	:S\$	6,502.00
Check Items (Estimated)	:S\$	500.00
Total	:S\$	7,002.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	38,218.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,782.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve some check items.