



Quotation

Non binding - Preview

Page 1/2

Company Ms First Capital Insurance Limited 6 RAFFLES QUAY #21-00 Singapore 048580	Customer Details: Mr RYOO JAE KWAN 499 CLEMENTI ROAD Singapore 599486	Document no. 03-07-2024 Document date 6151041856 Customer no. 195000106C Customer GST-ID 30001 Dealer 2024017891/1 Job order number 03-07-2024 Job order date Dass Anthonidas Service Advisor Christopher
--	--	--

License plate SMN9690X	Model code NU73NDA0	First registration 03-09-2019	VIN TMBKR7NU1K5025756	Model Karoq Ambition 1.5 TSI 110kW DSG w/PHI	Mileage 87,840
----------------------------------	-------------------------------	---	---------------------------------	--	--------------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNES				#8	280.00	305.20
	REPAIR						
9801B005	B&P DIAGNOSIS AND PROGRAMMING	1	pcs.	1,843.66	#8	480.00	523.20
57A807521	Cover For				#8	1,843.66	2,009.59
57A807521	REAR BUMPER (TOP)	1	pcs.				
57A807835	Cover For	1	pcs.	788.21	#8	788.21	859.15
57A807835	REAR BUMPER (BOTTOM)	1	pcs.				
57A807393	LHR BUMPER BRACKET (SIDE)	1	pcs.	77.13	#8	77.13	84.07
57A807394	Guide Piec	1	pcs.	77.13	#8	77.13	84.07
57A807394	RHR BUMPER BRACKET (SIDE)	1	pcs.	88.45	#8	88.45	96.41
57A807377	Guide Piec	1	pcs.	88.45	#8	88.45	96.41
57A807378	LHR BUMPER BRACKET (OUTER)	1	pcs.	88.45	#8	88.45	96.41
57A807378	Guide Piec	1	pcs.	77.69	#8	77.69	84.68
57A807863	RHR BUMPER BRACKET (OUTER)	1	pcs.				
	Attachment						
5Q0919133	REAR BUMPER BRACKET (CTR)	4	pcs.	1.63	#8	6.52	7.11
5Q0919275B	Seal Ring Satin Black	1	pcs.	206.04	#8	206.04	224.58
575807305B	Sensor Primed	1	pcs.	529.95	#8	529.95	577.65
57A945701A	REINFORCEMENT	1	pcs.	58.34	#8	58.34	63.59
	Reflector	1	pcs.				
5JA853687	LHR	1	pcs.	61.39	#8	61.39	66.92
	Inscriptio						
57A853687A	"SKODA" LETTERING	1	pcs.	85.90	#8	85.90	93.63
	Lettering						
565853621A	"KAROQ" LETTERING	1	pcs.	76.74	#8	76.74	83.65
	Skoda Embl	3	pcs.	840.00	#8	840.00	3,662.40
	LABOUR			800.00	#8	800.00	2,616.00
	Spray Painting						
	MS FIRST CAPITAL DIRECT						
	DOA:2/7/2024						
	TP VEH NO:SHF341P						
	SURVEY BY:						

Quotation valid till 10-07-2024

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#8	760.00	9,825.60	9%	952.70	10,585.60	11,538.30
Total	760.00	9,825.60		952.70	10,585.60	11,538.30


IDA Centre Singapore

g Kee Rd

pore 159104

eg. No.: 199101494Z

No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company

Ms First Capital Insurance

Limited

6 RAFFLES QUAY

#21-00

Singapore 048580

Customer Details:

Mr

RYOO

JAE KWAN

499 CLEMENTI ROAD

Singapore 599486

Document no.

03-07-2024

Document date

6151041856

Customer no.

195000106C

Customer GST-ID

30001

Dealer

2024017891/1

Job order number

03-07-2024

Job order date

Dass Anthonidas

Service Advisor

Christopher

License plate

SMN9690X

Model code

NU73NDA0

First registration

03-09-2019

VIN

TMBKR7NU1K5025756

Model

Karoq Ambition 1.5 TSI 110kW DSG

w/PHI

Mileage

87,840

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 20010068
4 days + 2 days
05/06/24
Res after repair
new & old parts

Supplementary or Omitted List



VEHICLE NUMBER: SLE4271P

MODEL

Tiguan Highline 1.4 I TSI 110kW N6 DSG

CLAIMS DETAILS

<u>No.</u>	<u>Description</u>	<u>Qty</u>	<u>Unit Pricing</u>	<u>Discount</u>	<u>Amount</u>
1	LABOUR (REPAIR END PANEL)	1	\$840.00	0%	\$840.00
2	SPRAY PAINT (END PANEL)	1	\$800.00	0%	\$800.00
TOTAL:					\$1,640.00

<u>No.</u>	<u>Item No.</u>	<u>Description</u>	<u>Qty</u>	<u>Unit Pricing</u>	<u>Discount</u>	<u>Amount</u>
1	57A919485C	Sensor Bracket ✓	1	\$53.68	0%	\$53.68
2	57A919485B	Sensor Bracket ✓	1	\$53.68	0%	\$53.68
3	57A919486B	Sensor Bracket ✓	1	\$38.15	0%	\$38.15
4	57A919486C	Sensor Bracket ✓	1	\$38.15	0%	\$38.15
5	D 180KU2A1	2k-Plastic Adhesive ✓	1	\$94.98	0%	\$94.98
6	D 822150A1	Bonding Agent For Plastic ✓	1	\$78.24	0%	\$78.24
7	N 10621301	Expanding Nut ✓	2	\$2.28	0%	\$4.56
TOTAL:						\$278.64

Total Labour & Parts

\$1,918.64

Total Working Days: 4 + 2 = 6 working days

Survey By:

Mr Rasul, LKK