

輝 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

03/07/2024

Owner: DARRN YEO FU WEN

ESTIMATE TO REPAIR NISSAN QASHQAI - SNP2595L

1pc	front LH fender	nett	\$	780.00
1pc	front LH fender protector	nett	\$	480.00
1pc	front LH sport rim	nett	\$	985.00
1pc	front LH kunckle arm	nett	\$	695.00
1pc	front LH wheel bearing	nett	\$	390.00
1pc	front LH lower arm	nett	\$	420.00
1pc	front LH absorber	nett	\$	455.00
1pc	front LH door	nett	\$	1,250.00
1pc	front LH door protector	nett	\$	425.00
1pc	front LH door glass firm garnish	nett	\$	285.00
1pc	front LH door glass firm top garnish	nett	\$	280.00
1pc	front LH door lower hinge	nett	\$	185.00
1pc	front LH door inner rubber	nett	\$	280.00
1pc	front LH door inner lock	nett	\$	495.00
1pc	rear LH door	nett	\$	1,200.00
1pc	rear LH door protector	nett	\$	425.00
1pc	rear LH door glass firm garnish	nett	\$	285.00
1pc	rear LH door glass firm top garnish	nett	\$	280.00
1pc	rear LH door lower hinge	nett	\$	180.00
1pc	rear LH door inner rubber	nett	\$	275.00
1pc	rear LH door inner lock	nett	\$	450.00
1pc	rear LH fender	nett	\$	1,850.00
1pc	rear LH fender protector	nett	\$	480.00
1pc	rear LH sport rim	nett	\$	985.00
1pc	rear LH kunckle arm	nett	\$	650.00
1pc	rear LH wheel bearing	nett	\$	390.00
1pc	rear LH lower arm	nett	\$	395.00
1pc	rear LH absorber	nett	\$	420.00
1pc	rear bumper	nett	\$	1,350.00
1pc	rear bumper diffuser	nett	\$	650.00

less 10%
balance c/f

\$	17,670.00
\$	1,767.00
\$	15,903.00



輝 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

03/07/2024

Owner: DARRN YEO FU WEN

ESTIMATE TO REPAIR NISSAN QASHQAI - SNP2595L

	balance b/f		\$ 15,903.00
2pcs	LH side Tyre @\$325.00	s.nett	\$ 650.00
	remove & refit LH front & rear undercarriage	\$	480.00
	remove & refit rear LH fender glass	\$	120.00
	remove & refit LH door glass	\$	150.00
	alignment	\$	160.00
	wiring	\$	100.00
	tuffkote	\$	150.00
	spray painting	\$	1,600.00
	labour charges	\$	1,600.00
	Total	\$	<u>20,913.00</u>

