



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070099/Rqp3m4
16 RAFFLES QUAY	Date:	23/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7209J	Veh. Inspected	SMF 717E
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24005849MFCT	Excess	\$0.00
Assign From	BETTY WONG	Assign Date	04/07/2024

2. Vehicle Details

Make & Model	PORSCHE 718 CAYMAN (982) PDK E6	C.C	1988
Engine No.	036647	Year of Reg.	03/12/2018
Chassis No.	WP0ZZZ98ZJK255381	Colour	GREY
Odometer	43318 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/40ZR19	PIRELLI	6
L/H Front Tyre	235/40ZR19	PIRELLI	6
R/H Rear Tyre	235/40ZR19	PIRELLI	6
L/H Rear Tyre	235/40ZR19	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/06/2024	Inspection Date	08/07/2024
Survey held at	27A TANJONG PENJURU SINGAPORE 609042 - REPAIRER: EUROKARS GROUP		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days