

LEANG AUTOMOTIVE
BLK 1 KAKI BIKIT AVE 6 #01-68
AUTOBAY S'PORE 417883 HP 90286516

VEHICLE No: SLT 3459T

Not Allowed
4/7/24
5 days
4800
Telephone After 12pm

1PC	REAR WINDSCREEN	11	\$1,288.10 X
1PC	REAR WINDSCREEN MOULDING	11	\$145.40 ✓
1PC	TAILGATE	11/12/13	\$1,842.00 ✓
1PC	TAILGATE OUTER HANDLE	11/12/13	\$369.40 X
2PCS	TAILGATE REFLECTORS @\$382.40	11/12/13	\$764.80 X
1PC	TAILGATE REAR LOGO	11	\$68.10 ✓
1PC	TAILGATE 'VALVE MATIC' EMBLEM	11	\$60.00 ✓
1PC	TAILGATE INNER LOCK	11	\$416.80 ✓
1PC	TAILGATE WEATHERSTRIP	11	\$366.20 ✓
1PC	TAILGATE INNER TRIM BOARD	11	\$467.30 X
1PC	REAR BUMPER	11	\$745.10 ✓
2PCS	REAR BUMPER DAMPERS @\$85.00	11	\$170.00 X
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11	\$130.00 X
2PCS	REAR BUMPER REFLECTORS @\$60.00	11	\$120.00 X
1PC	REAR END PANEL OUTER	11/12/13	\$642.00 ✓
1PC	REAR END PANEL LOWER	11/12/13	\$389.20 ✓
1PC	REAR END PANEL TOP GARNISH	11	\$381.80 ✓
2PCS	TAILLAMPS @\$395.00	11	\$790.00 X
2PCS	REAR FENDER INNER TRIM BOARDS @\$ 655.30	11	\$1,310.60 X
1PC	REAR FLOOR PANEL	11	\$1,410.80 X
			\$11,877.60
LESS 25%			\$8,908.20

S.NETT

1PC	REAR LICENCE PLATE	11	\$50.00 40
1PC	REAR WINDSCREEN SEALANT	11	\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00 20
1SET	TAILGATE INNER TRIM BOARD CLIPS	11	\$50.00 30
1SET	REAR BUMPER CLIPS	11	\$50.00 30
1SET	REAR BUMPER REVERSE SENSOR	11	\$280.00 X
TO CHECK WIRING			\$50.00 20
TO REMOVE & REPLACED REAR REVERSE SENSOR			\$80.00 30
TO REMOVE & REFIX REAR WINDSCREEN			\$150.00 120
TO REMOVE & REFIX TAILGATE MECHANISM			\$100.00 60
TO REMOVE & REFIX CUSHION UPHOLSTERY			\$120.00 60
TO REMOVE & REFIX REAR EXHAUST			\$100.00 X
TO REMOVE & REFIX FUEL TANK			\$100.00 X
TO REMOVE & REFIX REAR REVERSE CAMERA			\$100.00 X
TO SPRAY ANTI-RUST PROOFING			\$120.00 60
TO DIAGNOSIS & REPROGRAMME SYSTEM			\$180.00 X
LABOUR FOR PANEL BEATING			\$1,200.00 800

TO PUTTY & SPRAY PAINTING

TOTAL \$1,500.00 900
\$13,238.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5056.60
2572

3792.45

160

2050

6002.45

202

4801