

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGC5739X
Accident Date : 30-Jun-2024

Our Ref : 024128 (AIG) / CHAN

LEE BEE KEOW @ ONG BEE KEOW PATRICIA
134 BISHAN STREET 12
#04-163
Singapore 570134

No. : 07108

Date : 03-Jul-2024

PAGE : 1

NOT Authorised

11 Page 8

Meaning After Repair

4 days

ESTIMATED COST OF REPAIR FOR HONDA VEZEL SDY6113P

1 pc Tail gate		<i>RM</i> 934.30 ✓
1 pc Tail gate glass moulding-top		<i>RM</i> 30.00 ✓
1 pc Tail gate glass moulding-lower		<i>RM</i> 30.00 ✓
2 pcs Tail gate side moulding	@ S\$ 28.00	<i>RM</i> 56.00 ✓
1 pc Tail gate "VEZEL" emblem		<i>RM</i> 48.00 ✓
1 pc Rear bumper fascia		<i>RM</i> 583.20 ✓
1 pc Rear n/s bumper side		<i>RM</i> 182.30 X
1 pc Rear n/s bumper reflector		<i>RM</i> 189.20 X
1 pc Rear end panel		407.30 ✓

		2,460.30
Less 20% :		492.06

1 pc Rear w/s glass sealant
1 pc Rear bumper reverse sensor(set

To remove & refix rear windscreen
glass and conduct water leak test.

To remove roof lining, front and
rear seats, trim board and carpet

To apply undersealing

To putty and spray replaced parts

1,968.24 40sn
RM 60.00 sn
SEN 300.00 sn 200sn

150.00 1201

120.00 ?

60.00 301

500.00 ?

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGC5739X

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 7

Total : S\$ 3,758.24
=====

Singapore Dollars Three Thousand Seven Hundred
and Fifty Eight and Cents Twenty Four Only