

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **Lonpac Insurance Bhd**
300, Beach Road, #17-04 / 06,
The Concourse,
Singapore 199555

Attn : Motor Claims Department
Tel : 6250 7388
Fax : 6296 3767

Estimate bill : TT 24 / 24 / TP / WT

Registration No : SCK6308E

Make / model : MB E200 (213)

Mileage :

Date : 08 / 07 / 2024

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : YP8371X AND SCK6308E
ALONG JUNCTION OF UPPER PAYA LEBAR ROAD AND AIRPORT ROAD ON 02 JULY 2024 AT ABOUT
1900HRS.

1pc	Rear bumper		\$	1860	2,937.00	de ✓
3pcs	Rear bumper parking sensor (LH)	(Each \$365.00)	\$		1,095.00	X nn
6pcs	Rear bumper parking sensor seal ring	(Each \$21.00)	\$		126.00	new ✓
1pc	Rear bumper lip		\$	420	549.00	de ✓
1pc	Rear bumper lip chrome trimming		\$	342	541.00	eng ✓
1pc	Rear tail pipe chrome trimming (LH)		\$		487.00	X nn
	Sub A total :	2748	\$		5,735.00	
	Less 10% discount :	10%-2473.20	\$		573.50	
	A total :		\$		5,161.50	

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear bumper, rear bumper parking sensors (LH), rear bumper parking sensor seal rings, rear bumper lip, rear bumper lip chrome trimming, rear tail pipe chrome trimming (LH).

Heat / weld / panel beating rear end panel, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

To check and refit rear tail lamp wiring harness. , reverse sensor

Under coating on rear damaged portion.

Putty / primer application, spray painting rear end panel, rear bumper, rear bumper parking sensors (LH).

Grand final amount :

\$	900.00	250
\$	80.00	40
\$	200.00	X nn
\$	1,000.00	250
\$	7,341.50	540

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Taufik 97495749 / 62563561

9/7/24 @ 345

L/S Permitting after repair
taufik e lkhauto.com
2 days

2473.20
540
3013.20
LS\$2400
2 DAYS #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page

Acknowledged by Repairer

Signature:

Date: