

DING AUTO PTE LTD

Blk 176 #04-06
Sin Ming Drive (Sin Ming Autocare)
Singapore 575721
Tel: 92313123
Fax: 6452 0614

Vehicle:	SJD3833D
Model:	MERCEDES BENZ E200
Chassis:	WDD2130422A091430

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	REAR BUMPER	1	\$ 1,772.00	5%	\$ 1,417.60	X
2	REAR BUMPER RETAINER RHS	1	\$ 133.14	5%	\$ 106.51	X
3		1		5%	\$ -	
4		1		5%	\$ -	
5		1		5%	\$ -	
6		1		5%	\$ -	
7		1		5%	\$ -	
8		1		5%	\$ -	
9		1		5%	\$ -	
10		1		5%	\$ -	
11		1		5%	\$ -	
12		1		5%	\$ -	
TOTAL:					\$ 1,524.11	

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1	BUMPER CLIPS	1	\$ 50.00	✓
2	REAR BUMPER STICKER WRAP	1	\$ 800.00	7 (Bill)
3				850h
3				
SPECIAL NETT			\$ 850.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	PANEL BEAT- ACCIDENT AREA, REMOVE AND REFIT REAR BUMPER	\$ 600.00	120h
2	SPRAY PAINT- REAR BUMPER, REAR FENDER	\$ 600.00	X
3	CHECK WIRING AND CHECK ALIGNMENT	\$ 80.00	X
4			
5			
6			
7			
TOTAL:		\$ 1,280.00	

PARTS	\$ 1,524.11
LABOUR	\$ 1,280.00
SPECIAL NETT	\$ 850.00
TOTAL	\$ 3,654.11
GST 9%	\$ 328.87
FINAL TOTAL	\$ 3,982.98

Not withstanding

2 days

8820h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: