

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0531/2024/KS
DATE : 8-Jul-24
WIP : 22477

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS LILIAN CHEW GAIK LOOI
ADDRESS : 590 YIO CHU KANG ROAD
#02-01
SINGAPORE 787073
TELEPHONE : HP +65 98529635
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100425458-08
VEHICLE NO : **SKU 8419 H**
MODEL CODE : A4 1.8T FSI MU 8K203
MODEL YEAR : 19/8/2015
ENGINE NO : CJE 102530
CHASSIS NO : WAUZZZ8KFA128476
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Jul-24
PLACE OF ACCIDENT : CARPARK THOMSON GROVE CONDO

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 8419 H.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$	360.00	/
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00 1500	
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$	2,600.00 1650 + 200 = 1850	
5	TO RENEW RHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT	S/N \$	280.00	/
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	\$ 6,682.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 8419 H.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>See ✓</i>	1	\$ 3,061.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 286.00	
3	FRONT BUMPER SECURING STRIP - RH <i>?</i>	1	\$ 45.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ 286.00	
5	FRONT BUMPER GUIDE FRAME - RH <i>?</i>	1	\$ 103.00	
6	FRONT BUMPER VENT GRILLE- RH <i>?</i>	1	\$ 169.00	
7	FRONT HALOGEN FOG LAMP - RH <i>X</i>	1	TBC	
8	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	1	\$ 46.00	
9	HEADLIGHT - RH <i>See ✓</i>	1	\$ 2,646.00	
10	HEADLIGHT CONTROL UNIT - RH <i>?</i>	1	\$ 1,423.00	
11	HEADLIGHT POWER MODULE - RH <i>?</i>	1	\$ 762.00	
12	HEADLIGHT MOUNTING - RH <i>?</i>	1	\$ 147.00	
13	LIFT CYLINDER - RH <i>X</i>	1	\$ 252.00	
14	LIFT CYLINDER HOSE <i>X</i>	1	\$ 233.00	
15	FRONT FENDER - RH <i>See ✓</i>	1	\$ 1,185.00	
16	FRONT FENDER ATTACHMENT PARTS - RH <i>X</i>	1	\$ 67.00	
17	FRONT FENDER BRACKET - RH <i>See ✓</i>	1	\$ 64.00	
18	FRONT FENDER BRACE - RH LOWER <i>See ✓</i>	1	\$ 177.00	
19	FRONT FENDER CLOSING ELEMENT - RH <i>See ✓</i>	1	\$ 160.00	
20	FRONT FENDER SEAL - RH <i>X</i>	1	\$ 38.00	
SUB TOTAL SPARE PARTS		:	\$ 11,150.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 8419 H.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER - RH ?	1	\$	289.00
22	WHEEL HOUSING LINER ATTACHMENT PARTS - RH X	1	\$	50.00
23	BONNET bt -	1	\$	3,459.00
24	BONNET ATTACHMENT PARTS X	1	\$	184.00
25	BONNET HINGE - LH / RH X	2	\$	182.00
26	BONNET CATCH HOOK X	1	\$	174.00
27	BONNET EDGE PROTECTION ne /	1	\$	35.00
28	FRONT ALUMINIUM RIM - RH cut /	1	\$	1,565.00
29	FRONT ALUMINIUM RIM RUBBER VALVE - RH ne /	1	\$	5.00
30	SUNDRIES ?		\$	500.00
TOTAL SPARE PARTS		:	\$	17,254.00
TOTAL LABOUR CHARGES		:	\$	6,682.00
GRAND TOTAL		:	\$	23,936.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasm - Hp 900000000
: 09/07/24
: 6 days
: EXCESS = TBA
: Repair / Reg & paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT