

Date :

MS FIRST CAPITAL Insurance Pte Ltd
Attn: Motor Claims Department

Vehicle number : **SNP9768J**
Make and model : KONA ELECTRIC
Registration Date : 25/03/2024
Chassis number : KMHHE811VRU037034
Engine number : G4LLPS264781

Claim Officer : Robyn
Job No. :
Owner name : KHALID BIN AHM.
Date of Acc : 05/07/2024
Policy number A301105154 AH1
Claim Type : **TP**

Items :		2nd	Estimate	Revised
1	FRONT BUMPER CLIP X10	865952T500	\$ 20.00	
2	COVER ASSY-FR BUMPER UPR	86510BE100	\$ 726.00	
3	COVER ASSY-FR BUMPER LWR	86560BE110	\$ 1,100.00	
4	BRACKET ASSY-FR BUMPER SIDE,LH	86551BE000	\$ 20.00	
5	BRACKET ASSY-FR BUMPER SIDE,RH	86552BE000	\$ 20.00	
6	LAMP ASSY-HEAD,LH	92101BE130	\$ 2,759.00	
7	CLIP (X 3)	1420608250B	\$ 3.00	
8	GUARD ASSY-FRONT WHEEL,LH	86811BE000	\$ 175.00	
9	MOULDING-FRONT BUMPER,LH	86595BE000	\$ 74.00	
			\$ 4,897.00	
Less 25% Discount			\$ 1,224.25	
Material total			\$ 3,672.75	

Vehicle number : SNS9616Z

Body,Paint & Labour Items :		Estimate		
1	To carry out accident body repair - FRONT BUMPER	\$	1,260.00	
2	Complete putty and spray paint all affected areas - FRONT BUMPER / FRONT BUMPER GARNISH	\$	1,050.00	
Labour	Charges:	2nd	Estimate	Revised
3	TO REALIGN BOTH FRT HEADLAMP (S.NETT)	\$	40.00	
4	TO PERFORM WHEEL ALIGNMENT (S.NETT)	\$	140.00	
5	TO CHECK FOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER AC	\$	180.00	
6	TO REPROGRAMME AFTER ACCIDENT REPAIR (S.NETT)	\$	180.00	
7	SUNDRIES (S.NETT)	\$	40.00	
Total Labour		\$	2,890.00	\$ -
Total Parts		\$	3,672.75	\$ -
Excess		\$	-	\$ -
		\$	6,562.75	\$ -
Add GST 9%		\$	590.65	\$ -
Grand Total		\$	7,153.40	\$ -

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***