



AUTOLUTION

CarTimes Autolution Pte Ltd
160, Sin Ming Drive, Singapore 571634

#02-04 Singapore 575722

Email : claims@cartimes.com.sg

VEHICLE NO: SNH5134G

CHASSIS NO: JM6BP2SAAN1151155

DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)	
<u>PARTS (LIST ITEMS)</u>		
REAR BUMPER	900.36	\$ 1,200.00 de ✓
REAR BUMPER RETAINER LHS		\$ 150.00 X un ✓
REAR BUMPER REFLECTOR LHS		\$ 150.00 X un ✓
TAIL LAMP LHS	733.98	\$ 1,500.00 cut ✓
REAR FENDER LHS	1145	\$ 1,560.00 buc ✓
REAR FENDER INNER SHIELD LHS		\$ 300.00 X ✓
REAR BLIND SPOT ASSIST MODULE		\$ 1,900.00 X ✓
REAR BLIND SPOT ASSIST MODULE BRACKET		\$ 150.00 X ✓
	2779.34	\$ 6,910.00
	20% - 2223.47	\$ 1,382.00
		\$ 5,528.00
<u>SPECIAL NETT ITEMS</u>		
REAR BUMPER CLIPS 1 SET	30	\$ 50.00 net ✓ 30
Total		\$ 50.00
TOTAL PARTS		\$ 5,578.00

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	500
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	30
4	To provide anti-rust treatment on affected areas	\$ 100.00	30
5	Dignostic Check	\$ 100.00	✓
6	Remove & refit petrol tank	\$ 150.00	60
7	Blind spot assist programming	\$ 200.00	117
		1220	
	Labour Total :	\$ 3,850.00	
	TOTAL (PARTS & LABOUR):	\$ 9,428.00	

Tanfikh 97495749/62563561
 9/7/24 @ 5pm
 L/S Repair after repair
 Tanfikh @ 1khankh
 5 days