

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : 6050274773SG Date: 26th Jul 2024

Our Ref : CS/AIG24070174/Rvp3e2

M/s Aig Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16 Aig Building Singapore 079120 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMS 8946P ACCIDENT ON 08/07/2024

Instruction was received to inspect the vehicle Reg. No. SMS 8946P. The inspection was conducted on 11/07/2024 at the 24 Benoi Sector, Singapore 629857, Repairer: M/s Premium Automobiles Pte Ltd.

The following vehicle information was recorded:

Registration Number : SMS 8946P

Make/Model : Audi Q2 1.0 TFSI S Tronic

Year of Registration : 2020 Body Colour : Grey

Chassis Number : WAUZZZGA8KA083090

Engine Capacity : 999 cc Speedometer Reading : 41844 km

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is \$\$92,249.50 (Sin Dollars: Ninety-Two Thousand Two Hundred Forty-Nine and Fifty Cents only.) (Exclude check items \$\$56,780.50Nett) (Details see photographs enclosed)

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "uneconomical Total Loss".

| (a) | If the vehicle to be "Total Loss" |
|-----|-----------------------------------|
| | |

| Mar | zot. | Va | مرا |
|-----|------|-----|-----|
| Mar | ĸeι | v a | ıue |

S\$ 102,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 36,588.00)

Nett Liability

S\$ 65,412.00

Less: Excess

(<u>S</u>\$ 400.00)

S\$ 65,012.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) (Exclude check items \$\$56,780.50Nett) S\$ 92,249.50

Less:Excess

(S\$ 400.00)

Nett Liability

S\$

\$ 91,849.50

a) - (b) =

(S\$ 26,837.50)

=========

The amount of estimated saving of S\$26,837.50 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU

Licensed Appraiser

MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

<u>DISCLAIMER OF LIABILITY TO THIRD PARTIES:-</u> This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.