

ASS. REC. BY:

REF:

AGZ/

CS/AG/24070175/KNP3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$125K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

1B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLB44618

Yr Regn:

10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

BMW 218i

C.C

1499

Colour

M.D. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

69036

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA6V120805R 85615

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

5/7/24

D.O.I.

22/7/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/7 85615-97 Car (Red, \$3719.03, 30%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

[-> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	422E
Vehicle Details	
Vehicle No.:	SLB4461Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Jul 2024
Vehicle Make:	B.M.W.
Vehicle Model:	216i GRAN TOURER
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	37186091B38A15A
Chassis No.:	WBA6V120805R85615
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$32,724.00
Original Registration Date:	06 Oct 2020
First Registration Date:	06 Oct 2020
Transfer Count:	0
Actual ARF Paid:	\$37,814.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Oct 2030
PARF Rebate Amount:	\$28,360.00
Intended COE Rebate Details	
COE Expiry Date:	05 Oct 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,504.00
COE Rebate Amount:	\$24,020.00
Total Rebate Amount:	\$52,380.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 09 Jul 2024

OK

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07113

Vehicle Insured : SMX1405D
Accident Date : 05-Jul-2024

Date : 08-Jul-2024

Our Ref : 024134 (AUTO & GEN) / CHAN

PAGE : 1

TAN CHAI HWA
57 HILLVIEW AVENUE
#06-04
Singapore 669568

Not Withheld

*Recovery B4 painting
4 days*

\$ 8568.97

ESTIMATED COST OF REPAIR FOR BMW 216i SLB4461Z

1 pc	Front bumper fascia	<i>nd/cm</i>	1,187.80	✓
1 pc	Front bumper logo	<i>nc</i>	115.50	✓
1 pc	Front o/s bumper side grille	<i>cm</i>	140.72	✓
1 pc	O/s bumper side grille garnish	<i>B</i>	85.72	✓
1 pc	O/s side grille parking sensor	<i>sn</i>	285.50	X
1 pc	O/s side grille top garnish	<i>sn</i>	81.55	X
1 pc	O/s bumper parking sensor-out	<i>sn</i>	265.55	X
1 pc	Front o/s bumper side retainer	<i>DIY</i>	187.00	✓
1 pc	O/s front grille	<i>sn</i>	359.60	X
1 pc	O/s headlamp	<i>Bn</i>	2,650.20	✓
1 pc	O/s headlamp panel	<i>Bu</i>	161.85	✓
1 pc	O/s headlamp ballast	<i>sn</i>	1,157.15	X
1 pc	O/s headlamp control module	<i>sn</i>	365.10	X
1 pc	Bonnet	<i>Bn</i>	1,496.80	✓
1 pc	Front o/s fender	<i>nc</i>	708.90	X
1 pc	Front o/s fender inner shield	<i>sn</i>	165.10	X
			9,414.04	
		Less 5% :	470.70	

1 pc Front bumper rivet (set)

8,943.34
nc 30.00 sn ✓

To rewire damaged parts and refocus headlamp beam.

180.00 2ol

To putty and spray replaced parts

800.00 86ol

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMX1405D

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500/

700.00

Total : S\$10,653.34

Singapore Dollars Ten Thousand Six Hundred and
Fifty Three and Cents Thirty Four Only

12288

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMX1405D (AUTO & GEN)

Date : 23-07-2024

Accident Date : 05-07-2024

Our Ref : 024134 / CHAN

TAN CHAI HWA

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR BMW 216I SLB4461Z

1 PC	FRONT BUMPER SPONGE	CM	\$195.25	✓
1 PC	FRONT BUMPER REINFORCEMENT	R	\$940.20	✓
1 PC	FRONT W/S GLASS WASHER TANK	net	\$290.15	✓
1 PC	FRONT O/S BUMPER INNER PARTS	CM	\$295.10	✓
			\$1,720.70	
LESS 5%			\$86.04	
			<u>\$1,634.66</u>	

Singapore Dollars One Thousand Six Hundred Thirty Four And Cents Sixty Six Only

P 5724.31
S.P 1634.66
30.00
8N 1180.00
L 8568.97
↑