



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS/LPC24070176/Aqp3
300 BEACH ROAD	Date:	19/08/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 4597M	Veh. Inspected	SNC 1246U
Policy No.	-	Coverage	0
Claim No.	24/24/24/VC05/029502	Excess	\$0.00
Assign From	GERALD POH	Assign Date	09/07/2024

2. Vehicle Details

Make & Model	TOYOTA ALTIS	C.C	1598
Engine No.	1ZRY331232	Year of Reg.	23/12/2016
Chassis No.	MR053REH104557325	Colour	WHITE
Odometer	161852 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/45 R17	PIRELLI	6
L/H Front Tyre	215/45 R17	PIRELLI	6
R/H Rear Tyre	215/45 R17	PIRELLI	6
L/H Rear Tyre	215/45 R17	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/07/2024	Inspection Date	15/07/2024
Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #01-77 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days