

Shiau Chan (LKKAuto)

From: Rasul (LKKAuto)
Sent: Wednesday, 24 July 2024 2:35 PM
To: Sam San Joi UBI
Cc: Shiau Chan (LKKAuto)
Subject: Re: FINALIZE SLS3875E & PHOTOS

Hi Sam,

We will be advising our principal a cost of repair P/P of \$6,115.30.00 /- with 04 days of repair before GST, subject to their approval.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: Sam San Joi UBI <SanJoi.Sam@borneomotors.com.sg>
Sent: Wednesday, 24 July 2024 10:51 am
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINALIZE SLS3875E & PHOTOS