

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURANCE	CE LTD	Ref:	CS/INC24070187/Aqh3	
	75 BRAS BASAH RO	DAD SINGAPORE 189557	Date:	02/10/2024	
	INCOME CENTRE	BINGAPORE 109337	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLW 4291L	Veh. Inspected	SNB 7856A	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1285159-002	Excess	\$0.00	
	Assign From	ENG HUEY HUEY	Assign Date	10/07/2024	
2.	2. Vehicle Details				
	Make & Model	B.M.W. 216I GT	C.C	1499	
	Engine No.	34345262B38A15A	Year of Reg.	31/08/2018	
	Chassis No.	WBA2D920005K81215	Colour	GREY	
	Odometer	114229 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/45 R18	MICHELIN	6	
	L/H Front Tyre	225/45 R18	MICHELIN	6	
	R/H Rear Tyre	225/45 R18	MICHELIN	6	
	L/H Rear Tyre	225/45 R18	MICHELIN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	08/07/2024	Inspection Date	10/07/2024 (12:00)	
	Survey held at HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days