



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI24070188/Avp3

Date: 23/08/2024

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1503Z	Veh. Inspected	SNF 6294G
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005990MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	09/07/2024

2. Vehicle Details

Make & Model	TOYOTA NOAH HYBRID	C.C	1797
Engine No.	2ZR2M84799	Year of Reg.	13/06/2022
Chassis No.	ZWR800506553	Colour	BLACK
Odometer	142640 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	KAPSEN	6
L/H Front Tyre	195/65 R15	KAPSEN	6
R/H Rear Tyre	195/65 R15	KAPSEN	6
L/H Rear Tyre	195/65 R15	KAPSEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/07/2024	Inspection Date	10/07/2024
Survey held at	AUTOMOBILE HUB ENTERPRISE - 1 KAKI BUKIT AVENUE 6 #01-15 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days