

Customer Name:

ng kwang soon

Vehicle No:

SNM5184K

Date:

8-Jul-24

Contact No 1:

91778353

Email 1:

[ngkwangsoon@hotmail.com](mailto:ngkwangsoon@hotmail.com)

Brand &amp; Model:

MG ZS EV SE

Repair Day(s):

3

Contact No 2:

Email 2:

Chassis/VIN No:

LSJW74090PZ257644

Quoted By:

**PARTS / MATERIAL**

No	Description	Unit Price	Qty	Disc %	Net Price
1	REAR BUMPER UPPER	\$ 794.00	1		\$ 794.00
2	REAR BUMPER LOWER	\$ 1,469.00	1		\$ 1,469.00
Sub-Total (Parts Price)					\$ 2,263.00

**LABOUR**

No	Description	Price
1	TO REMOVE & REPLACE REAR BUMPER.	\$ 400.00
2	TO RESPRAY REAR BUMPER.	\$ 400.00
3	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00
Sub-Total (Labour Price)		\$ 950.00

**Remarks**

- Prices are valid for 7 calendar days from quotation date.
- Scope of work is based on visual inspection. Should there be additional damage found during repair, it will be informed and quoted separately.
- A request for detailed repair quote in addition to this quotation will be subject to an administrative fee of 20% of the detailed quotation value, which will be refunded if the repairs are undertaken by Eurokars.
- Repair day(s) is only an estimate and subject to confirmation after repair starts.
- Prices quoted solely for cash repair not for insurance claim purpose
- For further enquiry or to make an appointment, please contact us at +65 6331 0680.

Parts Price	\$ 2,263.00
Labour Price	\$ 950.00
Total Price	\$ 3,213.00
GST	\$ 289.17
<b>GRAND TOTAL</b>	<b>\$ 3,502.17</b>

**EUROKARS SERVICES PTE LTD**
**CUSTOMER ACCEPTANCE**

\_\_\_\_\_  
Authorized Signature

\_\_\_\_\_  
Customer Signature