

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Date: 09th September 2024 Your Ref: ACS/105/009/2023/093 (LK)

Our Ref: CS1/SPF24070203/Eqp3m4

M/s Automotive Engrg. & MGT. Division (TP)

Accident Claims Section (Spore Police Force) Police Logistics Base (PLB) 1 Hemmant Road Singapore 438675 (The Motor Claims Department)

Attn: Lai Peng Chong

Dear Sir / Madam.

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJP 2435M INSURED VEHICLE: TP 462D ACCIDENT DATE: 10/05/2023

We thank you for your instruction on 08/07/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJP 2435M from M/s Direct Asia Insurance (Singapore) Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicle SJP 2435M.
- c) Survey report by Verisk with colour photographs.
- d) Tax invoice from M/s Auto Insure Pte Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJP 2435M

Make & Model : Mitsubishi Lancer EX 2.0 (A) : JMYSTCY4A9U000561 : 2009 Chassis Number

Year of Registration



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

- 2. Our finding is that the repair cost of \$5,850.00 (before GST) quoted by M/s Direct Asia Insurance (Singapore) Pte Ltd is fair & reasonable.
- 3. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.

Yours Faithfully,

1

CHEN TSUE YEE Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.