



Your Ref : SNM24D203934/C01

Date: 01<sup>st</sup> August 2024

Our Ref : CS/CTI24070208/Eqp3m4

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE CB 356C  
ACCIDENT ON 09/07/2024**

Instruction was received to inspect the vehicle Reg. No. CB 356C. The inspection was conducted on 11/07/2024 at the premises of M/s Jin Auto Services Pte Ltd, Blk 14 Defu Lane 10, #01-410/412, Singapore 539195.

The following vehicle information was recorded:

Registration Number	: CB 356C
Make/Model	: Toyota Hiace 2.8 DX Auto
Year of Registration	: 2023
Body Colour	: Silver
Chassis Number	: GDH2012030308
Engine Capacity	: 2754 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the front and front n/s portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	52,000.00 - 56,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	0.00)
Nett Liability	S\$	52,000.00 - 56,000.00
		=====

Vehicle Inspected By:



CHEN TSUE YEE  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.