

No f Accident
hm
3 days
take photo. He say
2/5 \$ 950

REPAIR ESTIMATE

Claim Type: Third Party Claim

Date : 24 Jun 2024

Attn:

Vehicle Num : SMZ288X

Motor Claims Department

Make/Model : TOYOTA HARRIER G GRADE

Owner: LAI CHIN MENG

Chassis # : JTEKB3GH40J003943

DOA: 24 Jun 2024

Engine # : 8ARZ146073

Yr. Of Manu : 2018

No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				

1	ROOF SIDE PANEL RH	1	S\$ 1850.00	S\$ 1850.00	X
2	ROOF SIDE PANEL BLACK MOULDING RH	1 set	S\$ 290.00	S\$ 290.00	✓
3	FRONT DOOR WINDSOR VISOR	1	S\$ 280.00	S\$ 280.00	X
				Amt S\$	1,850.00
DISCOUNT:				25% S\$	462.50
				Subtotal S\$	1,387.50

No.	Description	Qty	U/P	Amt
Section: LABOUR				

4	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		S\$	750.00	300
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		S\$	800.00	550
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION-SEAT, TRIM GARNISH, TRIM LINER CARPET.		S\$	120.00	117 X
7	REMOVE AND REINSTALL FRONT WINDSCREEN GLASS TO ASSIST REPAIR			250.00	120
				Amt S\$	1920.00

JKK Auto Consultants has conducted a visual inspection of the following:


- 4. The survey of the damaged parts.
- 4. The display of damaged parts.
- 4. The parts are subject to confirmation.
- 4. The parts are subject to "Without Prejudice" basis.
- 4. The legal modification is allowed.

Supplementary items must be surveyed and is subject to the approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal: S\$ 1,387.50
 LABOUR Subtotal: S\$ 1,920.00
 Total: S\$ 3,307.50

290
252
217.1
970
1187.1
950

bizSAFE₃