

No of Accident
3 days
take photo. 100% 4-
2/s # 950

REPAIR ESTIMATE

Claim Type: Third Party Claim Date : 24 Jun 2024
 Attn: Lonpac Insurance Bhd Vehicle Num : SMZ288X
 Motor Claims Department Make/Model : TOYOTA HARRIER G GRADE
 Owner: LAI CHIN MENG Chassis # : JTEKB3GH40J003943
 DOA: 24 Jun 2024 Engine # : 8ARZ146073
 Yr. Of Manu : 2018


No.	Description	Qty	U/P	Amt
<u>Section: LIST ITEMS</u>				
1	ROOF SIDE PANEL RH	1	S\$ 1850.00 S\$	1850.00 X
2	ROOF SIDE PANEL BLACK MOULDING RH	1	S\$ 290.00 S\$	290.00 ✓
3	FRONT DOOR WINDSOR VISOR	1	S\$ 280.00 S\$	280.00 X
				Amt S\$ 1,850.00
DISCOUNT: 25%				S\$ 462.50
Subtotal				S\$ 1,387.50

No.	Description	Qty	U/P	Amt
<u>Section: LABOUR</u>				
4	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		S\$	750.00 300
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		S\$	800.00 550
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION-SEAT, TRIM GARNISH, TRIM LINER CARPET.		S\$ 117	120.00 X
7	REMOVE AND REINSTALL FRONT WINDSCREEN GLASS TO ASSIST REPAIR			250.00 120
Amt S\$				1920.00

LKK Auto Consultants henceforth
 the Repairer of the following:
 - To remove before/after spray painting
 - To change damaged parts
 - To replace parts are subject to condition
 - Third party survey is on a "Written Report"
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be received
 is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer
 Signature:
 Date:

LIST ITEMS Subtotal: S\$ 1,387.50
 LABOUR Subtotal: S\$ 1,920.00
 Total: S\$ 3,307.50



Joo Hak Kee Auto Pte. Ltd.

bizSAFE

290
 252
 2175
 970
 1187.5
 950