

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0543/2024/KS  
**DATE** : 11-Jul-24  
**WIP** : 22810

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/7/2024**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : M/S NEWCRANE HOLDINGS PTE LTD  
**ADDRESS** : 244 WESTWOOD AVENUE  
#06-53  
SINGAPORE 648366  
**TELEPHONE** : HP +65 98501753  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220045142-02  
**VEHICLE NO** : **SKJ 5360 U**  
**MODEL CODE** : A5 SPORTBACK 2.0 TFSI  
**MODEL YEAR** : 16/4/2013  
**ENGINE NO** : CDN 269715  
**CHASSIS NO** : WAUZZZ814CA051030  
**MILEAGE** : KM  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 9-Jul-24  
**PLACE OF ACCIDENT** : OPEN CARPARK AT JALAN BAHAR

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKJ 5360 U**

| S/N                         | NATURE OF JOBS                                                                                                                                  |          | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.                            | S/N \$   | 360.00               |                               |
| 2                           | TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE                                                                              | S/N \$   | 400.00               |                               |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$       | 2,400.00             |                               |
| 4                           | TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.                                                                                                   | \$       | 2,000.00             |                               |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                  | S/N \$   | 292.00               |                               |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                 | <b>:</b> | <b>\$</b>            | <b>5,452.00</b>               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 5360 U**

|                              |                                    |            | <b>DAMAGED PARTS &amp; PRICES</b> |                 |
|------------------------------|------------------------------------|------------|-----------------------------------|-----------------|
| <b>S/N</b>                   | <b>PARTS DESCRIPTION</b>           | <b>QTY</b> | <b>S/NETT</b>                     | <b>REMARKS</b>  |
| 1                            | FRONT BUMPER                       | 1          | \$                                | 3,254.00        |
| 2                            | FRONT BUMPER FIXING PARTS          | 1          | \$                                | 286.00          |
| 3                            | FRONT BUMPER SECURING STRIP - LH   | 1          | \$                                | 45.00           |
| 4                            | FRONT BUMPER CLOSING ELEMENT - LH  | 1          | \$                                | 286.00          |
| 5                            | FRONT BUMPER AIR GUIDE GRILLE - LH | 1          | \$                                | 285.00          |
| 6                            | FRONT HALOGEN FOG LAMP             | 1          |                                   | TBC             |
| 7                            | FRONT WHEEL SPOILER - LH           | 1          | \$                                | 75.00           |
| 8                            | FRONT BUMPER GUIDE PIECE - LH      | 1          | \$                                | 56.00           |
| 9                            | FRONT BUMPER TOP COVER             | 1          | \$                                | 160.00          |
| 10                           | HEADLIGHT - LH                     | 1          | \$                                | 2,808.00        |
| 11                           | LED HEADLIGHT MOUNTING             | 1          | \$                                | 155.00          |
| 12                           | LIFT CYLINDER - LH                 | 1          | \$                                | 319.00          |
| 13                           | FRONT FENDER - LH                  | 1          | \$                                | 1,283.00        |
| 14                           | FRONT FENDER ATTACHMENT PARTS - LH | 1          | \$                                | 67.00           |
| 15                           | FRONT FENDER BRACKET - LH FRONT    | 1          | \$                                | 71.00           |
| 16                           | FRONT FENDER BRACKET - LH REAR     | 1          | \$                                | 71.00           |
| 17                           | FRONT FENDER RIVET                 | 4          | \$                                | 17.00           |
| 18                           | FRONT FENDER BRACE - LH            | 1          | \$                                | 182.00          |
| 19                           | FRONT FENDER CLOSING ELEMENT - LH  | 1          | \$                                | 172.00          |
| 20                           | FRONT FENDER SEAL - LH             | 1          | \$                                | 23.00           |
| <b>SUB TOTAL SPARE PARTS</b> |                                    | <b>:</b>   | <b>\$</b>                         | <b>9,615.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 5360 U**

|                             |                                           |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|-------------------------------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                         | QTY | S/NETT                 | REMARKS |
| 21                          | SIDE MEMBER COVER - LH LOWER FRONT        | 1   | \$ 19.00               |         |
| 22                          | FRONT WHEEL HOUSING LINER - LH            | 1   | \$ 219.00              |         |
| 23                          | WHEEL HOUSING LINER ATTACHMENT PARTS - LH | 1   | \$ 50.00               |         |
| 24                          | SUNDRIES                                  |     | \$ 500.00              |         |
| <b>TOTAL SPARE PARTS</b>    |                                           | :   | <b>\$ 10,403.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                                           | :   | <b>\$ 5,452.00</b>     |         |
| <b>GRAND TOTAL</b>          |                                           | :   | <b>\$ 15,855.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT