

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0543/2024/KS
DATE : 11-Jul-24
WIP : 22810

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : M/S NEWCRANE HOLDINGS PTE LTD
ADDRESS : 244 WESTWOOD AVENUE
#06-53
SINGAPORE 648366
TELEPHONE : HP +65 98501753
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220045142-02
VEHICLE NO : **SKJ 5360 U**
MODEL CODE : A5 SPORTBACK 2.0 TFSI
MODEL YEAR : 16/4/2013
ENGINE NO : CDN 269715
CHASSIS NO : WAUZZZ814CA051030
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Jul-24
PLACE OF ACCIDENT : OPEN CARPARK AT JALAN BAHAR

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKJ 5360 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$	360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N \$	400.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	500
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		: \$	5,452.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 5360 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rep</i>	1	\$ 3,254.00	+
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 286.00	+
3	FRONT BUMPER SECURING STRIP - LH	1	\$ 45.00	+
4	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 286.00	+
5	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 285.00	+
6	FRONT HALOGEN FOG LAMP	1	TBC	+
7	FRONT WHEEL SPOILER - LH	1	\$ 75.00	+
8	FRONT BUMPER GUIDE PIECE - LH	1	\$ 56.00	+
9	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 160.00	+
10	HEADLIGHT - LH <i>cracked</i>	1	\$ 2,808.00	✓ <i>2746.40</i>
11	LED HEADLIGHT MOUNTING <i>new</i>	1	\$ 155.00	+
12	LIFT CYLINDER - LH <i>new</i>	1	\$ 319.00	+
13	FRONT FENDER - LH <i>Rep</i>	1	\$ 1,283.00	+
14	FRONT FENDER ATTACHMENT PARTS - LH	1	\$ 67.00	+
15	FRONT FENDER BRACKET - LH FRONT	1	\$ 71.00	+
16	FRONT FENDER BRACKET - LH REAR	1	\$ 71.00	+
17	FRONT FENDER RIVET	4	\$ 17.00	+
18	FRONT FENDER BRACE - LH	1	\$ 182.00	+
19	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 172.00	+
20	FRONT FENDER SEAL - LH	1	\$ 23.00	+
SUB TOTAL SPARE PARTS		:	\$ 9,615.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 5360 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	SIDE MEMBER COVER - LH LOWER FRONT <i>Ren</i>	1	\$ 19.00	<i>X</i>
22	FRONT WHEEL HOUSING LINER - LH <i>Ren</i>	1	\$ 219.00	<i>X</i>
23	WHEEL HOUSING LINER ATTACHMENT PARTS - LH <i>Ren</i>	1	\$ 50.00	<i>X</i>
24	SUNDRIES <i>?</i>	<i>rec</i>	\$ 500.00	<i>? 9.78 ✓</i>
TOTAL SPARE PARTS		:	\$ 10,403.00	
TOTAL LABOUR CHARGES		:	\$ 5,452.00	
GRAND TOTAL		:	\$ 15,855.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian G*
SURVEYED DATE : *12/07/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT