

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SMA6212G

MAKE & MODEL: TOYOTA SIENTA

Not Authorised
Lkh
morus
16/7/24
L/S 47000
Take photo After 1st
5 days

TAILGATE	body DD	1712.30	\$1,865.90	✓
TAILGATE OUTER GARNISH	But/cne		\$321.30	✓
TAILGATE LOGO	neu	82.50	\$91.50	✓
TAILGATE INNER LOCK	Daye	599.10	\$676.80	✓
TAILGATE INNER PULL HOLDER	11		\$48.30	α
TAILGATE STRIKER	11		\$62.00	α
TAILGATE INNER TRIMBOARD	11		\$585.40	X
TAILGATE WEATHERSTRIP	Tw1	476.60	\$536.40	✓
TAILGATE LAMP L/R X2	cne		\$856.60	✓
TAILGATE NUMBER PLATE LAMP L/R X2	11		\$188.40	X
TAILGATE WINDSCREEN MOULDING SET	neu	150.20	\$216.80	✓
TAIL LAMP L/R X2	11		\$1,286.20	X
REAR BUMPER	DD	480.20	\$625.60	✓
REAR BUMPER CENTRE BLACK GARNISH	DD	242.50	\$312.50	✓
REAR BUMPER SIDE BLACK GARNISH L/R X2	1/8 cur 06511		\$386.80	IPC 193.40
REAR BUMPER SIDE REFLECTORS L/R X2	11		\$188.20	α
REAR BUMPER SIDE RETAINER L/R X2	11		\$280.80	α
REAR BUMPER SIDE BRACKET L/R X2	11		\$248.60	α
REAR BUMPER TOW COVER	SUC		\$89.60	X
REAR BUMPER CENTRE LAMP GARNISH	NS		\$96.40	X
REAR BUMPER CENTRE LAMP	cne		\$286.70	✓
REAR BUMPER REVERSE SENSOR X2	malhutan		\$560.80	2000s/N
REAR BUMPER REVERSE SENSOR BRACKET SET	11		\$96.30	X
REAR END PANEL TOP PANEL	body DD		\$689.70	✓
REAR END PANEL INNER PANEL	body DD	566.10	\$989.10	✓
REAR END PANEL GARNISH	Tw1		\$288.10	✓
REAR FENDER SIDE TRIMBOARD L/R X2	del/ton	645.10 x 2 = 1290.20	\$1,686.80	1290.20
SPARE TYRE PANEL TOP BOARD	8u		\$456.10	X
SPARE TYRE PANEL TOOLTRAY	11		\$536.80	X
SPARE TYRE PANEL	R		\$968.90	α
REAR EXHAUST MUFFLER	11		\$864.70	α
			\$16,388.10	
Less 25%			\$4,097.03	
			\$12,291.08	
1 set REAR BUMPER CLIPS	neu		\$60.00	30
REVERSE CAMERA	SUC		\$380.00	X
TAILGATE TRIMBOARD CLIPS	11		\$50.00	X
TAILGATE OUTER GARNISH CLIPS	11		\$50.00	X
TAILGATE WINDSCREEN SEALANT	neu		\$120.00	40
TAILGATE WINDSCREEN SPONGE	neu		\$80.00	20
END PANEL GARNISH CLIPS	11		\$60.00	X

END PANEL SEALANT	111	\$100.00	40
REAR NUMBER PLATE WITH CASING	Sen	\$70.00	40
REAR FENDER SIDE TRIMBOARD CLIPS	11	\$180.00	X
		\$1,150.00	
TO CHECK REAR WIRING		\$50.00	20
TO REPLACE REAR REVERSE SENSOR		\$80.00	30
TO REPLACE REAR REVERSE CAMERA	11	\$100.00	X
TO REPLACE REAR WINDSCREEN		\$150.00	120
TO REMOVE AND REPLACE TAILGATE FITTINGS		\$120.00	60
TO REMOVE AND REPLACE REAR INTERIOR TRIMS & GARNISH		\$200.00	80
TO PROVIDE LABOUR, WORKMANSHIP		\$1,400.00	850
TO SPRAY PAINT ON AFFECTED PANELS		\$1,400.00	1000
TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	11	\$160.00	X
RUST PROOFING		\$150.00	50
		\$3,810.00	
Total		\$17,251.08	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 8235-50
 252
 6176-63
 370
 2210
 8786-63
 202
 7005