



QUOTATION

CODE: L0002
CUSTOMER: LONPAC INSURANCE BHD
ADDRESS: 300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

PAGE NO.: 1
DOCUMENT NO.: 1229
DOCUMENT DATE: 11/06/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: 1
WIP NO.: 14300
REF. NO.:
DATE IN: 18/12/2023
EXT. WTY: 0
MILEAGE:

CONTACT NO.: 6250 7388 *sterechen@lkkauto.com*
MODEL: MAZDA3 1.5L SDN DELUXE BLACK L
CHASSIS NO.: JM6BN22A8K0265147
ENGINE NO.: P520566283
REG NO.: SLL4040C *Stev (LKK)*
REGN DATE: 19/12/2018 *20/6/24 12.11pm*

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	LONPAC TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA.			792	1,584.00	S
SUB	TO RESPRAY REAR BUMPER & REINFORCEMENT.			756	2,835.00	S
SUB	TO TRANSFER REVERSE SENSORS.			180	330.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			180	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			180	300.00	S
SUB	SUNDRIES.					
BFYD-50-221	REAR BUMPER BM/BN W/SENSOR	1.00	1,143.51	*NO STOCK	29	50.00 S
B45A-56-146A	FASTENER	4.00	2.36	STOCK		1,143.51 S
BBM4-50-355	RIVET	4.00	3.71	STOCK		9.44 S
BHN1-50-0Z1A	GROMMET, SCREW	4.00	2.36	*NO STOCK		14.84 S
BCKA-50-EM1	TAPE, PROTECTOR	3.00	7.42	*NO STOCK		9.44 S
B45A-50-260	REINFORMENT REAR BM	1.00	576.77	STOCK		22.26 S
BHN1-51-153	GASKET(R), RR.COMB. BM/BN	1.00	26.47	STOCK		576.77 S
BHN1-51-163	GASKET(L), RR.COMB. BM/BN	1.00	26.47	STOCK		26.47 S

	GST Code	Rate	Service/Goods	GST
Parts	O	-		-
Surcharge	S	9.00%	7,178.20	646.04
Labour				
Menus				

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross	7,178.20	646.04	7,824.24
Less: Deposit**	0.00	0.00	0.00
Amount Due	7,178.20	646.04	7,824.24

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 155
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 15909
Sales Tel: 6603 6118 Service Tel: 6
Sales Fax: 6476 7073 Service Fax:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: